

Form approved, Budget Bureau No. 1004-0135, Expires August 31, 1985

Form 3160-5 (November 1983) (Formerly 9-331)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

30-041-20250

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME Bluitt San Andres Unit Sec-14	
2. NAME OF OPERATOR PLAINS PETROLEUM OPERATING COMPANY		8. FARM OR LEASE NAME	
3. ADDRESS OF OPERATOR 415 W. WALL, SUITE 1000 MIDLAND, TX 79701		9. WELL NO. 9	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface  Unit Letter I, 1980' FSL & 660' FEL		10. FIELD AND POOL, OR WILDCAT Bluitt San Andres Assoc.	
14. PERMIT NO.		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec.14, T8S, R37E	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4016 GL		12. COUNTY OR PARISH Roosevelt	
		13. STATE NM	

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐ PULL OR ALTER CASING ☐  
 FRACTURE TREAT ☐ MULTIPLE COMPLETE ☐  
 SHOOT OR ACIDIZE ☐ ABANDON\* ☒  
 REPAIR WELL ☐ CHANGE PLANS ☐  
 (Other) ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐ REPAIRING WELL ☐  
 FRACTURE TREATMENT ☐ ALTERING CASING ☐  
 SHOOTING OR ACIDIZING ☐ ABANDONMENT\* ☐  
 (Other) ☐  
 (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

In response to your letter dated Jan. 20, 1994, PPOC plans to plug and abandon this well and requests approval of the following plugging program.

1. Set plug across perfs 4518'-79' (10' sx) 140' cmt. plug 4605'-4465', Tag plug.
2. Cut and recover approximately 3000' of 5-1/2" casing
3. Set 10 sx plug at TOC 130' cmt. plug centered on 5 1/2" stub. Tag plug.
- \* -> 4. Set 10 sx plug at surface csg shoe @ 298', 264x cmt. plug 348'-248' tag plug.
5. Set surface plug with marker 50' minimum cmt. surface plug.

\* Additional plug: Cmt. Plug (120') 2200'-2080'

18. I hereby certify that the foregoing is true and correct

SIGNED Bonnie Hubbard

TITLE Administrative Assistant

DATE Jan. 28, 1994

(This space for Federal or State office use)

APPROVED BY approved as modified.

TITLE

DATE

\*See Instructions on Reverse Side