

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5370

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Union Oil Company of California	8. Farm or Lease Name State "A-36"
3. Address of Operator P. O. Box 671 - Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER M , 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 7-S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat
15. Elevation (Show whether DF, RT, GR, etc.) 4090' GR 4101' DF	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-7-71 Verbal approval obtained from Mr. J. D. Ramey on proposed plugging operations as follows:

Plug No. 1 - 25 sacks at 4566' to 4548' to cover perforations
Plug No. 2 - 25 sacks at 4-1/2" casing stub or at top of salt.
Plug No. 3 - 25 sacks at 366' base of stub- in and out of 8-5/8" casing shoe.
Plug No. 4 - 10 sacks at 15' to Surface

Install abandonment marker, as per N.M.O.C.C. rules and regulations.
Cleaning & leveling location for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNED <i>J. R. Gray</i>	J. R. Gray	TITLE District Drilling Supt.	DATE 5-11-71
APPROVED BY <i>J. D. Ramey</i>		TITLE SUPERVISOR DISTRICT	DATE MAY 13 1971
CONDITIONS OF APPROVAL, IF ANY:			

RECEIVED

MAY 12 1971

OIL CONSERVATION COMM.
HOBBS, N. M.