

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
NA	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Moran Exploration, Inc.	Lewis Com.
3. Address of Operator	9. Well No.
400 Wilco Bldg., Midland, Texas 79701	1
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER North 660 FEET FROM THE South 1980 FEET FROM	Vada Penn
THE West LINE, SECTION 35 TOWNSHIP 8-S RANGE 34-E NMPM.	
11. Elevation (Show whether DF, RT, GR, etc.)	12. County
4245 GL.	Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set CIBP @ 9575' and dump 20' of cement w/ dump bailer.
2. Free point 5½" casing and cut off at approximately 4900'.
3. Spot 40 sxs plug @ 4850' - 4950' (100' Plug).
4. Spot 50 sxs plug @ 3900' - 4000' (100' Plug).
5. Cut 8 5/8" casing @ 1000'.
6. Spot 50 sxs plug @ 950' - 1050' (100' Plug).
7. Spot 10 sxs plug @ surface, cut off head, weld plate on, clean location.

* Work will commence August 1, 1979.

100' PLUG 50' IN & 50' OUT OF SURFACE CSG

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Division Operations Mgr. DATE 6-27-79

APPROVED BY Jerry Sexton
Dist. I. Supv
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____ DATE JUL 6 1979