.O. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old
SANTA FE	NEW MEXICO OIL CON	SERVATION COMMISSION	C-102 and C-103 Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State 🗙 Fee
OPERATOR			5. State Oil & Gas Lease No.
	-		K-4128
(DO NOT USE THIS FORM FOR PRUSE "APPLICAT	CY NOTICES AND REPORTS ON DPOSALS TO DRIVE OR TO DEEPEN OR THUS TON FOR PERMIT - " FORM C-101) FOR SU	I WELLS BACK TO A DIFFERENT RESERVOIR.	
1. OTL GAS WELL WELL	OTHER-		7. Unit Agreement Name
2. Name of Operator			8. Farm or Lease Name
CITIES SERVICE OIL	CONDANY		
3. Address of Operator	. LUMPANY		9. Well No.
P.O. Box 69. Hobbs	, New Mexico 88240		,
4. Location of Well			10. Field and Pool, or Wildcat
1 1 1	980 FORT FROM THE SOUTH	(1)	Bluitt San Andres
UNIT LETTER	FORT FROM THE		CALLED Sell Allo (CS
West	ON 16 OWNSHIP 85	2.25	
THE HOJE LINE, SECTI	ONOWNSHIPOD	RANGENMF	
	15. Elevation (Show whathe	DF, RT, GR, etc.)	12. County
X/////////////////////////////////////	3995 DF		Roosevelt
1^{ϵ} . Check		Dependent of National Dependent of	
	Appropriate Box To Indiana 1		
NOTICE OF I	NTENTION TO	SUBSEQUE.	NT REPORT OF:
PERFORM REMEDIAL WORK	FL. AND ABAND	E PEREDIAL WORK	
TEMPORARILY ABANDON	TIL ONE ADAMIN	COMMENCE DRILLING OPNS.	ALTERING CASING
PUL. OR ALTER CASING		CASING TEST AND CEMENT JOB	PLUG AND ABANDONMENT
POLL OR ALTER CASING	CHARAN PLAND		L
OTHER		OTHER	

17. Describe Proposed or Completed Operations (Clearly state all pertinent coulds, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 4844, PBTD 4825, Perfs 4789--4814. We propose to re-stimulate the above well on December 8, 1971 using the following procedure:

- 1. Set BOP
- 2. Pull rods and tubing
- Run packer & tubing. Set packer at approximately 4700'. 3.
- 4. Load annulus W/modified brine.
- Treat with 8000 gal. 15% Unisol, modified gelled brine and rock salt, using 5. friction reducer, at 5--6 B/M rate at approximately 3200 spi surface pressure
- 6. Flush with brine, shut in until pressure bleeds down to zero.
- 7. Swab back until well cleans up. 8.
- Pull tubing and packer. Re-run tubing, pump & rods. Put well on production.

18.1	hereby certify (hat the	information	above is	true	and couplete	to the	0-31-01	ENV.	knowledge	and ¹	helief.
10.1	nereby centry i	mat the	mation	above is	, LIUN	and comprete	te the	0.141-0		anowredge	anu	nener.

5 IGNED	· · · ·	TITLE _	District Administrative Sup. DATE	Dec. 7	<u>, 1971</u>
	er Simper in Le Distance				× 1971
APPROVED BY	F ANY:	TITLE _	DATE		

REPENCED

17 ang 18 19 ang 19

O E CEUSERVATION COMM. COSEC I. L. L.