

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
K-3724

SUNDY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
SEE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. ☐ OIL ☐ GAS ☐ WELL OTHER- Salt Water Disposal	7. Unit Agreement Name
2. Name of Operator SAGE ENERGY COMPANY	8. Farm or Lease Name Cabot State
3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702	9. Well No. 4
4. Location of well UNIT LETTER G, 1980 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 8S RANGE 36-E NMPM.	10. Field and Pool, or Wildcat Vada Penn
15. Elevation (show whether DF, RT, GR, etc.) 4102'	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Present Casing:

17" hole size 12 3/4" csg. set at 395' with 450 sx Class "C"
11" hole size 8 5/8" csg. set at 3946' with 250 sx Class "C"
7 7/8" hole size 4 1/2" csg. set at 9880' with 500 sx Class "H"
2 3/8" tubing at 9719

Plugging proposal:

Set CIBP above perforation with 35' cement plug.
Load hole with mud of 10# brine, 25# gel per bbl.
cut off 8 5/8" at approximately 7500'. plug across 4 1/2" shoe with 50' in and 50' out and tag.
100' plug at 9200' (Wolfcamp formation)
100' plug at 5500' (Glorieta formation)
100' plug across salt at approximately 2250', plug across surface shoe.
10 sx plug at surface, surface market.

Top of cement behind 8 5/8" is at 3300', will need to cut and pull 8 5/8" or perf and sqz plug at surface casing shoe and tag plug.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED: _____ TITLE: Production Clerk DATE: 5-9-88

Orig. filed by
Paul Kautz
Geologist

APPROVED BY: _____ TITLE: _____ DATE: MAY 11 1988

CONDITIONS OF APPROVAL, IF ANY: