

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K 3724	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Sage Energy Company		Cabot State
3. Address of Operator		9. Well No.
P. O. Drawer 3068, Midland, Texas 79702		4
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER <u>A</u> <u>1980</u> FEET FROM THE <u>East</u> LINE AND <u>1980</u> FEET FROM		
THE <u>North</u> LINE, SECTION <u>32</u> TOWNSHIP <u>8S</u> RANGE <u>36E</u> N.M.P.M.		
15. Elevation (Show whether DF, RT, GR, etc.)		12. County
4102 GL		Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set Cast Iron Bridge Plug and 35' cement at 9730'
Cut 5 1/2" and pull as much as possible 5000'±
100' plug 1/2 in and 1/2 out at 5 1/2" stub.
100' at Top of San Andres Top 4049'.
100' at shoe of 8 5/8" 1/2 in and 1/2 out 3946' unless San Andres is close to 3946'.
Cut 8 5/8" and pull at low as possible.
100' at 8 5/8" stub.
100' at 12 3/4" shoe 395'.
10 sxs surface and marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Production Clerk</u>	DATE <u>Jan. 11, 1985</u>
ORIGINAL SIGNED BY <u>W. H. WINTON</u>		
APPROVED BY <u>[Signature]</u>		
TITLE <u></u> DATE <u>JAN 15 1985</u>		
CONDITIONS OF APPROVAL, IF ANY:		