

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-041-20412
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	
Murphy Hinton	
8. Well No.	1
9. Pool name or Wildcat	Bluitt San Andres, Assoc.

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	2. Name of Operator John Yates Jr - Oil Operator
3. Address of Operator 331 W Main Ste A	4. Well Location Unit Letter <u>A</u> : <u>660</u> Feet From The <u>North</u> Line and <u>660</u> Feet From The <u>East</u> Line Section <u>22</u> Township <u>8S</u> Range <u>37E</u> NMPM <u>Roosevelt</u> County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4008' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal permission was obtain by Bill Prichard.

Plug and Abandon as Follow

1. Run and set cmt ret to 2830, Squeezed 50 sx under ret.
2. Stung out of ret and spotted 50 sx cmt. woc
3. tagged plug at 720'
4. perforated 5 1/2 csg 4 shots at 406'.
5. Broke circ between 5 1/2 x 8 5/8 , circ cmt to surfs.
6. Left 100' cmt in 5 1/2 above perms.
- 7 Tagged plug and put 10 sx cmt to surfs.

Approved as to plugging of the Well Bore.  
Liability under bond is retained until  
surface restoration is completed.

5/10/00  
WITNESSED BY Bill Prichard.

CHANGES WERE APPROVED BY Bill Prichard.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Johnny Gabaldon TITLE Field Supervisor DATE 5-17-2000  
TYPE OR PRINT NAME Johnny Gabaldon TELEPHONE NO. 505/748-1471

(This space for State Use)

APPROVED BY GARY W WINK TITLE OC FIELD REPRESENTATIVE II/STAFF MANAGER DATE JAN 09 2003

CONDITIONS OF APPROVAL, IF ANY:

GWW