

COPY TO U. C. C.
UNITED STATES DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY
SUBMIT IN TRIPLICATE*
(Other instructions on reverse side)

Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.
~~W-04168-A~~ NM041698-A
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR
H. L. Brown, Jr.

3. ADDRESS OF OPERATOR
Post Office Box 2237, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

990' FWL, 1550' FNL

14. PERMIT NO. _____ 15. ELEVATIONS (Show whether DT, RT, GR, etc.)
4043' GR

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Kirkpatrick Federal

9. WELL NO.
8

10. FIELD AND POOL, OR WILDCAT
Bluitt (Wolfcamp)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 11, T8S, R37E

12. COUNTY OR PARISH
Roosevelt

13. STATE
NM

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

<p>TEST WATER SHUT-OFF <input type="checkbox"/></p> <p>FRACURE TREAT <input type="checkbox"/></p> <p>SHOOT OR ACIDIZE <input type="checkbox"/></p> <p>REPAIR WELL <input type="checkbox"/></p> <p>(Other) <input type="checkbox"/></p>	<p>PULL OR ALTER CASING <input type="checkbox"/></p> <p>MULTIPLE COMPLETE <input type="checkbox"/></p> <p>ABANDON* <input checked="" type="checkbox"/></p> <p>CHANGE PLANS <input type="checkbox"/></p>	<p>WATER SHUT-OFF <input type="checkbox"/></p> <p>FRACURE TREATMENT <input type="checkbox"/></p> <p>SHOOTING OR ACIDIZING <input type="checkbox"/></p> <p>(Other) <input type="checkbox"/></p>	<p>REPAIRING WELL <input type="checkbox"/></p> <p>ALTERING CASING <input type="checkbox"/></p> <p>ABANDONMENT* <input type="checkbox"/></p>
--	---	--	---

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and surface pertinent to this work.)

It is planned to plug and abandon by following procedure:

1. Run cast iron bridge plug and set in 5 1/2" OD csg at 8000'
2. Cut off 5 1/2" OD csg at or near the cement top at 5810' and recover same
3. Run tubing and spot 100 foot cement on top of bridge plug at 8000', 100 foot cement across 5 1/2" casing stub (cut off), 100 ft. cement across 8 5/8" casing shoe at 3190' and 50 ft. cement plug at surface of hole w/4" pipe marker above ground level.
4. Cut off bradenhead; recover all surface producing equipment and level location

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

RECEIVED

JUN 5 1979

U. S. GEOLOGICAL SURVEY
HOBBS, NEW MEXICO

18. I hereby certify that the foregoing is true and correct.

SIGNED James Davidson

TITLE Prod-Acctg. Supv.


DATE 6-1-79

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

*See Instructions on Reverse Side



RECEIVED

JUN 12 1979

OIL CONSERVATION COMM.
HOBBS, N. M.