

NO. OF COPIES RECEIVED		
DISTRIBUTION		
ANTA FE		
ILE		
A.S.G.S.		
LAND OFFICE		
PERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator EL RAN, INC.		
Address of Operator P. O. BOX 911, LUBBOCK, TEXAS 79408		
Location of Well UNIT LETTER <u>H</u> , <u>2200</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>34</u> TOWNSHIP <u>7-S</u> RANGE <u>32-E</u> NMPM.		

7. Unit Agreement Name
8. Farm or Lease Name Bergstrom
9. Well No. 1
10. Field and Pool, or Wildcat Chaveroo SA
11. Elevation (Show whether DF, RT, GR, etc.) 4486 KB
12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
RECALL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

El Ran, Inc. plugged and abandoned the above referenced well 11/09/82 using the following procedure:

1. Set CBP 4100' with 100' plug above BP
2. ~~Shoot~~ ^{SHOT} 4 1/2" off and load hole with 10# mud with 100' cement plug. Tagged plug
3. Set 100' cement plug from 1750' to 1650'. Tagged plug
4. Set 10' plug with marker at surface.

Perfs: 4142 - 4294

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Vice-President</u>	DATE <u>4/16/85</u>
APPROVED BY <u>Jackie R. Griffin</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>APR 18 1985</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

APR 17 1985

O.C.D.
HOBBS OFFICE