

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. 30-041-20534

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator PENNZOIL COMPANY	8. Farm or Lease Name Roosevelt "6" State
3. Address of Operator P.O. Drawer 1828, Midland, Texas 79703	9. Well No. 1
4. Location of Well UNIT LETTER <u>G</u> <u>1980</u> FEET FROM THE <u>North</u> LINE AND <u>1980</u> FEET FROM THE <u>East</u> LINE, SECTION <u>6</u> TOWNSHIP <u>7-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Todd, N.W.
15. Elevation (Show whether DF, RT, GR, etc.) 4265.9'	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Verbal approval to plug this well granted by Mr. Les Clements on 7/30/80.

PROPOSED OPERATIONS:

- 8/80 A. Set CIBP @ 4140' (36' above top perf). Dump 35' cmt on top.
B. Circulate hole w/mud (10# brine w/25#/bbl of salt gel).
C. RIH w/tbg & spot 100' of cmt from 900' to 1000' (top of salt).
D. Ten sx cmt plug at surface with marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>J. V. Sullins</u>	TITLE <u>Operations Engineer</u>	DATE <u>7/30/80</u>
Orig. Signed by <u>Jerry Sexton</u>		
APPROVED BY <u>Dis. L. Supv.</u>	TITLE _____	DATE <u>AUG 14 1980</u>
CONDITIONS OF APPROVAL, IF ANY:		