

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240

Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR MURPHY OPERATING CORPORATION		8. FARM OR LEASE NAME CONE FEDERAL	
3. ADDRESS OF OPERATOR P. O. Drawer 2648, Roswell, New Mexico 88202-2648		9. WELL NO. 23	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660' FSL & 660' FWL, Unit Ltr. M, Sec. 27, T7S, R32E		10. FIELD AND POOL, OR WILDCAT Chaveroo San Andres	
14. PERMIT NO.		15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4479' GL, 4491' KB	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 27, T7S, R32E	
		12. COUNTY OR PARISH Roosevelt	
		13. STATE New Mexico	

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	
(Other) <input type="checkbox"/>			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

8 5/8" casing set @ 1884', cemented w/400 sxs., circulated.
4 1/2" casing set @ 4430', cemented w/200 sxs.
Perforation 4200-4273'.

Propose to plug and abandon well in following manner:

1. Set cement plug from 4325-4150'. Tag plug.
2. Cut and pull 4 1/2" casing from approximately 3000-2800'.
3. Set 130' cement plug centered on 4 1/2" casing stub. Tag plug.
4. Set 120' cement plug across 8 5/8" casing 1944-1824'. Tag plug.
5. Set 50' cement plug at surface.
6. Install dry hole marker.

Well will be plugged in accordance with Roswell Resource Area General Requirements for Permanent Abandonment of Wells. BLM will be notified 24 hours prior to initiation of plugging activities.

18. I hereby certify that the foregoing is true and correct

SIGNED Melinda K. Hickman
Melinda K. Hickman

TITLE Production Supervisor

DATE May 18, 1989

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE APPROVED
PETER W. CHESTER

JUN 2 1989

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

RECEIVED

SEP 12 1989

OCD
NOBBS OFFICE