

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P.O. Box 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG-3640	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Read & Stevens, Inc.			8. Farm or Lease Name DAVID STATE
3. Address of Operator P.O. Box 1518, Roswell, NM 88201			9. Well No. 1
4. Location of Well UNIT LETTER <u>P</u> . <u>660</u> FEET FROM THE <u>East</u> LINE AND <u>660</u> FEET FROM THE <u>South</u> LINE. SECTION <u>32</u> TOWNSHIP <u>7S</u> RANGE <u>35E</u> NMPM			10. Field and Pool, or Wildcat Wildcat
5. Elevation(Show whether DF,RT,GR,etc.) 4237.1' GL			12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>	PLUG AND ABANDON	<input checked="" type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>	CHANGE PLANS	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>		
OTHER	<input type="checkbox"/>		

Describe Proposed or Completed Operations(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Notify NM OCD @ 396-6161 in Hobbs.
2. Set 4 1/2" CIBP @ 4450', cap w/35' cmt w/dump bailer.
3. Circ hole w/salt gel mud.
4. Cut csg @ +3050', spot 100' plug half in & half out of csg stub, 3000'-3100', spot 75sx Class "C" cmt.
5. Spot 100' plug @ 1785'-1685' across 8 5/8" csg shoe @ 1735'. Spot 45sx Class "C" cmt WOC 4hrs & tag plug.
6. Spot 30' plug @ surface, 0-30', spot 10sx Class "C" cmt.
7. Cut off anchors, clean loc, install dry hole marker & prep loc for inspection.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. J. Sexton TITLE Drilling and Production Manager DATE 7-10-85

ORIGINAL SIGNED BY JERRY SEXTON
APPROVED BY DISTRICT I SUPERVISOR TITLE DATE JUL 12 1985

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUL 11 1967

PAGE