

Form 3160-5  
(November 1983)  
(Formerly 9-331)

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

ATE\*  
(Other instructions on reverse side)

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

NM044216

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Bluitt San Andres Unit Sec.13

8. FARM OR LEASE NAME

9. WELL NO.

16

10. FIELD AND POOL, OR WILDCAT

Bluitt San Andres Assoc.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec.13, T8S, R37E

12. COUNTY OR PARISH 13. STATE

Roosevelt

NM

SUNDRY NOTICES AND REPORTS ON WELLS  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PLAINS PETROLEUM OPERATING COMPANY

3. ADDRESS OF OPERATOR

415 W. WALL, SUITE 1000 MIDLAND, TX 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

Unit Letter P, 660' FSL & 660' FWL

14. PERMIT NO.

15. ELEVATIONS (Show whether OF, RT, GR, etc.)

3989 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF


FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)


REPAIRING WELL

ALTERING CASING

ABANDONMENT\*


17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

In response to your letter dated Jan. 20, 1994, PPOC plans to plug and abandon this well and requests approval of the following plugging program.

1. Set plug across perfs 4658'-86' <sup>18</sup>(10' sx). 140' cmt. plug 4742'-4602'. Tag plug
2. Cut and recover approximately 770' of 5-1/2" casing
3. Set 10' sx plug across TOC. 100' cmt. plug centered on 5 1/2" steel. Tag plug.
4. Set 10' sx plug at surface csg shoe @ 526'. 100' cmt. plug 576 - 476'. Tag plug
5. Set surface plug with marker. 50' minimum cmt. surface plug.

API No. 30-041-20853

18. I hereby certify that the foregoing is true and correct

SIGNED

*Donnie Husband*

TITLE

Administrative Assistant

DATE

Jan. 28, 1994

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*Approved as modified*

\*See Instructions on Reverse Side