



(SUBMIT IN TRIPLICATE)

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

Land Office **New Mexico**
Lease No. **01171**
Unit **100**

RECEIVED JUN 7 1960

SUNDRY NOTICES AND REPORTS ON WELLS

NOTICE OF INTENTION TO DRILL		SUBSEQUENT REPORT OF WATER SHUT-OFF	
NOTICE OF INTENTION TO CHANGE PLANS		SUBSEQUENT REPORT OF SHOOTING OR ACIDIZING	
NOTICE OF INTENTION TO TEST WATER SHUT-OFF		SUBSEQUENT REPORT OF ALTERING CASING	
NOTICE OF INTENTION TO RE-DRILL OR REPAIR WELL		SUBSEQUENT REPORT OF RE-DRILLING OR REPAIR	
NOTICE OF INTENTION TO SHOOT OR ACIDIZE		SUBSEQUENT REPORT OF ABANDONMENT	
NOTICE OF INTENTION TO PULL OR ALTER CASING		SUPPLEMENTARY WELL HISTORY	
NOTICE OF INTENTION TO ABANDON WELL	X		

(INDICATE ABOVE BY CHECK MARK NATURE OF REPORT, NOTICE, OR OTHER DATA)

Well No. **2** is located **130** ft. from **N** line and **330** ft. from **W** line of sec. **22**
May 26, 19 **60**
Hinkle
Wildcat (Field) **Chaves** (County or Subdivision) **New Mexico** (State or Territory)
NW/4 Sec. 22 (1/4 Sec. and Sec. No.) **15-S** (Twp.) **30-E** (Range) **10PM** (Meridian)

The elevation of the **ground** floor above sea level is **4069** ft.

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Total depth **3300'** - Dolomite.
Verbal approval obtained from Mr. J. A. Knauf 5/25/60 to plug & abandon well as follows:

100' plug from 3200' to 3300'
 100' plug from 2420' to 2520'
 100' plug from 1600' to 1700'
 100' plug from 700' to 800'
 50' plug from 125' to 175' *
 50' plug from 0' to 50'

Set marker and clean up location.

* 8-5/8" casing @ 157'

I understand that this plan of work must receive approval in writing by the Geological Survey before operations may be commenced.

Company **Nearburg & Ingram**

Address **P. O. Box 847**

Roswell, New Mexico

By **Robert M. [Signature]**
Title **Clerk**