Form 9-331 (May 1963)

## UNITED ATES SUBMIT IN TRIPLICATE\* (Other instructions on reverse side) Form approved. Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY			NM-0338-A		
SUNDRY NOTI (Do not use this form for propost Use "APPLICA"	CES AND REPORTS O	N WELLS ck to a different servoir.	6. IF INDIAN, ALLOTTEE		
1.	CUNIT AGREEMENT NA	ME			
SUNDRY NOTICES AND REPORTS ON WELLS  (Do not use this form for proposals to drill or to deepen or plug back to a difference of the control of			CENTIT AGREEMENT NA  STATE LUCK:  NO. FARM OR LEASE NAM  Peery Feder:  9. WELL NO.  1	Lattle Lucky Lake Unit	
2. NAME OF OPERATOR			ME S. FARM OR LEASE NAM	PS. FARM OR LEASE NAME	
TEXACO Inc.			Peery Feder	Lest the Lucky Lake Unit 8. FARM OR LEASE NAME Peery Federal 9. WELL NO.	
3. ADDRESS OF OPERATOR P. O. Box 728. Hobbs. New Mexico 88240			9. WELL NO.	1	
P. O. Box 728, Hobbs, New Mexico 88240  4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*			10. FIELD AND POOL, OF		
See also space 17 below.) At surface			1	y Lake Devonian	
1980' FNL & 1980' FEL, Unit Letter G, Section			11. SEC., T., B., M., OR B SURVEY OR AREA	·	
			SUBVET OR ADDA		
29, T-15-S, R-30-E, Chaves Co., New Mexico.			29-15S-30E		
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.)		12. COUNTY OR PARISH		
Regular	3981' DF		Chaves	N.M.	
16. Check Ap	propriate Box To Indicate Na	iture of Notice, Report, or	Other Data		
NOTICE OF INTENT	HON TO:	SUBSE	QUENT REPORT OF:		
		W. 6770 CVVV CVV	REPAIRING W	PRIT.	
	ULL OR ALTER CASING	WATER SHUT-OFF FRACTURE TREATMENT	ALTERING CA	·	
	BANDON*	SHOOTING OR ACIDIZING	ABANDONMEN		
	HANGE PLANS		lete in Penn	X Temp. Het.	
(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)					
17. DESCRIBE PROPOSED OR COMPLETED OPER proposed work. If well is direction	ATIONS (Clearly state all pertinent	details, and give pertinent date	es, including estimated date ical depths for all markers	e of starting any and zones perti-	
nent to this work.) *	, <b>3</b>		•	·	
1. Rig up unit, ins	tall BOP			•	
z. mig up unito, inb	odii boi.				
2. Run CIBP in $5\frac{1}{2}$ " cement on top of	casing to 11,000' plug. Test casi	& set @ 10,000 ng w/500#.	'. Dump 30' (	(125#)	
3. Perforate 5½" ca	sing w/2 JSPF @ 8	561, 65, 92, 98	•		
4. Run tubing and p set packer @ 848	acker, spot 200 g 0'.	al. 15% NE Acid	across perfor	ations,	
5. Acidize perfs. 8 ball sealers bet	561'-8598' w/2500 ween stages. Flu	gal. 15% NEA Ir sh w/50 bbls. tr	n 5-500 gal st reated fresh v	ages w/3 water.	
6. Swab, pull tubing	g & packer.				
7. Abandon Devonian					
8. Penn Zone - Shut Held For further	-In (Classified Ti Study.	R-O, To Be Recor	nditioned - Oi	.1) -	
15 1 banks and Nills in Late 1	two and correct				
18. I hereby certify that the folegoing is		sst. Dist. Supt.	DATE	<b>2</b> 8-76	
(This space for rederal or State offic	e use)				
		. wiiST	DATE		
CONDITIONS OF APPROVAL, IF A	NY:	ED. WELL MUSEL	DAIR		
	TITLE  NY:  UNLESS FURTHER APPROV  BE PUT TO BENEFICAL USE  BE PUT TO BENEFICAL	OR PLUG			
111/11/2	BE PUT TO BENEN PT	_ 19/6			
A Built	BE PUT TO BENEFICAL  BE PUT TO BENEFICAL  See Instructions	on Reverse Side			