

Form 9-331  
(May 1963)UNITED STATES  
DEPARTMENT OF THE INTERIORSUBMIT IN TRI  
(Other instruction  
verse side)ATE\*  
# reForm approved.  
Budget Bureau No. 42-R1424.

GEOLOGICAL SURVEY OF N. M. O. C. C.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. Artesia - NM 01171
2. NAME OF OPERATOR TEXACO Inc.		6. IF INDIAN, ALLOTTEE OR TRIBE NAME NONE
3. ADDRESS OF OPERATOR P. O. Box 728 - Hobbs, New Mexico		7. UNIT AGREEMENT NAME NONE
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface  This well is located 660' from the South Line, and 660' from the West Line of Section 34, T-15-S, R-30-E, Chaves County, New Mexico.		8. FARM OR LEASE NAME K. McIntosh Federal
14. PERMIT NO. Regular		9. WELL NO. 1
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4028' (D. F.)		10. FIELD AND POOL, OR WILDCAT Henshaw West Grayburg
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 34, T-15-S, R-30-E
		12. COUNTY OR PARISH Chaves
		13. STATE N. M.

## 16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\* ☒

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

Subject well has been plugged and abandoned as follows:

1. Pull the Pump equipment, mud up hole, prepare to cut casing.
2. Spot Plug No. 1, from 3337' to 3075', 50 Sx. Cement.
3. Cut off 4 1/2" O. D. Casing @ 1025', and recover same.
4. Spot Plug No. 2, from 1025' to 975', 20 Sx. Cement.
5. Spot Plug No. 3, from 690' to 590', 25 Sx. Cement.
6. Spot Plug No. 4, Surface plug, 15 Sx. Cement, Install 4" O. D. marker extending 4' above ground level. Clean the location for inspection by the USGS Office, Artesia, New Mexico. Plug and abandon was completed 8:30 P. M. May 13, 1967.

18. I hereby certify that the foregoing is true and correct

SIGNED

(This space for Federal or State office use)

TITLE

Assistant District Supt.

DATE

May 17, 1967

APPROVED BY  
CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

\*See Instructions on Reverse Side

AUG 8 1967

D. C. C.