

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

HOOBS OFFICE O. C. C.
JUN 5 11 34 AM '68

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B-10419-22	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator		Pebble Queen	
3. Address of Operator		8. Farm or Lease Name	
P. O. Box 1659, Midland, Texas 79701		State WV	
4. Location of Well		9. Well No.	
UNIT LETTER <u>K</u> , 1980 FEET FROM THE <u>South</u> LINE AND 1980 FEET FROM		10. Field and Pool, or Wildcat	
THE <u>West</u> LINE, SECTION <u>2</u> TOWNSHIP <u>13-S</u> RANGE <u>31-E</u> NMPM.		Caprock Queen	
15. Elevation (Show whether DF, RT, GR, etc.)		12. County	
4401.7 GR		Chaves	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This Unit was terminated June 1, 1968. We plan to place a 25 sack cement plug across the open hole 3041-3021 and 130' into the 5½". Pull some 800' of 5½" and place 25 sacks into the stub. Place 25 sacks at the surface pipe shoe 8 5/8, 278' with 10 sacks at surface.

A proper marker and clean-up will be made.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O. H. Crews Administrative Coordinator DATE June 4, 1968

APPROVED BY [Signature] TITLE [Signature] DATE [Signature]

CONDITIONS OF APPROVAL, IF ANY:

Min. d. between plugs