TRIBUTION FE		
FE	<del> </del>	Supersedes Old C-102 and C-103
	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
Σ. Σ		
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State Z Fee
OPERATOR		5. State Oil & Gas Lease No.
		B-10416-25
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE *APPLICATION FOR PERMIT -** (FORM C-101) FOR SUCH PROPOSALS.)		
I.  OIL A GAS  WELL OTHER-		7. Unit Agreement Name North Caprock Queen Unit 2
2. Name of Operator		8. Farm or Lease Name
Anadarko Production Company		Tract #22
3. Address of Operator		9. Well No.
P. O. Box 647 Artesia, New Mexico 88210		1
4. Location of Well	THE CONTROL TO A TRANSPORT OF THE PARTY OF T	10. Field and Pool, or Wildcat
UNIT LETTER	660 FEET FROM THE South LINE AND 1980 FEET F	Caprock Queen
	- GOO WAR DOUGH	
THE THOSE LINE. SEC	TION	MPM. (())
11000		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	11111111 1403 GL	Chaves
16. Chec	k Appropriate Box To Indicate Nature of Notice, Report or	
	· · · · · · · · · · · · · · · · ·	ENT REPORT OF:
101102 01	111 E11 101 101	
DESCRIN REMEDIAL WORK	PLUG AND ABANDON REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK		₹
TEMPORABILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	
	OTHER	
OTHER	1 1 <b>1</b>	
	Operations (Clearly state all pertinent details, and give pertinent dates, inclu	ding estimated date of starting any proposed
17. Describe Proposed or Completed work) SEE RULE 1103.	olug at 29001, numbed 251 cement on top of plug	. Shot off oil
17. Describe Proposed or Completed work) SEE RULE 1103.  Set abandonment patring at 8301.  from 2101 to 3101	Operations (Clearly state all pertinent details, and give pertinent dates, including at 2900; pumped 25; cement on top of plug Pumped 30 sacks cement from 770; to 870;. Pumped. Ten sacks cement at surface with heavy muder and cleaned up location.	. Shot off oil ped 35 sacks cement
17. Describe Proposed or Completed work) SEE RULE 1103.  Set abandonment patring at 830'.  from 210' to 310'  Set surface marks	olug at 2900', pumped 25' cement on top of plug Pumped 30 sacks cement from 770' to 370'. Pum . Ten sacks cement at surface with heavy mud	. Shot off oil ped 35 sacks cement
17. Describe Proposed or Completed work) SEE RULE 1103.  Set abandonment patring at 830'.  from 210' to 310'  Set surface marks	Pumped 30 sacks cement from 770' to 870'. Pumped 30 sacks cement at surface with heavy muder and cleaned up location.  tion above is true and complete to the best of my knowledge and belief.	. Shot off oil ped 35 sacks cement between all plugs.
17. Describe Proposed or Completed work) SEE RULE 1103.  Set abandonment patring at 830'.  from 210' to 310'  Set surface marks	Pumped 30 sacks cement from 770' to 370'. Pumped 30 sacks cement at surface with heavy muder and cleaned up location.	• Shot off oil ped 35 sacks cement between all plugs.
17. Describe Proposed or Completed work) SEE RULE 1103.  Set abandonment patring at 830'.  from 210' to 310'  Set surface marks	Pumped 30 sacks cement from 770' to 870'. Pumped 30 sacks cement at surface with heavy muder and cleaned up location.  tion above is true and complete to the best of my knowledge and belief.	. Shot off oil ped 35 sacks cement between all plugs.