

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION
Mar 8 11 39 AM '66

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
B - 8822	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Injection Well	7. Unit Agreement Name North Central Caprock 8. Queen Unit Queen Unit
2. Name of Operator GREAT WESTERN DRILLING COMPANY	9. Well No. 8000 #8
3. Address of Operator Box 1659, Midland, Texas	10. Field and Pool, or Wildcat Caprock Queen
4. Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 14 TOWNSHIP 13-S RANGE 31-E NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) 4414 GR.	12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
 NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The hole will be loaded with mud. A 25 sack cement plug will be set in the 5-1/2" casing (3030 to 2855) this is above the perforations (3041 - 3050). A 25 sack plug will be set in the stub. A 25 sack plug will be placed at the shoe of the surface pipe with 5 sacks in the surface. A proper marker will be placed and a clean up made. Starting date as soon as possible.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *O. H. Crews* **O. H. Crews** TITLE **Administrative Coordinator** DATE **March 7, 1966**

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: