OF COPIES RECEIVED	Form C - 103
	Supersedes Old
DISTRIBUTION	C-102 and C-103
NEW VEXTCO OUL CONSERVATION COMMISSION	Effective 1-1-65
FILE	5a. Indicate Type of Lease
U.S.G.S.	State XX Fee
LAND OFFICE	5. State Oll & Gas Lease No.
OPERATOR	E-7659
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
	7. Unit Agreement Name
OIL GAS WELL OTHER. WATER INJECTION WELL	ROCK QUEEN UNIT
2. Nume of Operator	8. Farm or Lease Name
	TRACT NO. 32
GREAT WESTERN DRILLING COMPANY	9. Well No.
3. Address of Operator	92 -2
P. O. BOX 1659 MIDLAND TX 79701	10. Field and Pool, or Wildcat
t teastion of Well	
UNIT LETTER B 660 FEET FROM THE NORTH LINE AND 1980 FEET FRO	CAPROCK QUEEN
UNIT LETTER FEET FROM THE LINE AND	
m.a. 22 13-9 31-E	
THEEAST LINE, SECTION 22 TOWNSHIP 13-S RANGE 31-E NMPN	«ΧΗΗΗΗΗΗΗΗΗΗ
	12. County
TITICITIES TO A State of the second	CHA¥ES
GR 4433'	
16. Check Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
	IT REPORT OF:
NOTICE OF INTENTION TO: SUBSEQUER	
PERFORM REMEDIAL WORK	ALTERING CASING
COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	
PULL OR ALTER CASING	
OTHER	
0THER	
	interested data of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includi	ng estimated date of starting any propose
work) SEE RULE 1103.	
Temporarily abandoned in February of 1971.	
Temporarily abandoned in February of 1971.	
Temporarily abandoned in February of 1971.	o offset producers
Temporarily abandoned in February of 1971.	o offset producers
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod	o offset producers luce.
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod	o offset producers luce. will be used between
Temporarily abandoned in February of 1971.	o offset producers luce.
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w	o offset producers luce. will be used between all plugs.
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to proc Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom.	io offset producers luce. will be used between all plugs. C Top & BIM. OF SHE
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. (2) 100' cement plug @ stub of production casing cut.	io offset producers luce. will be used between all plugs. C Top & BIM. OF SHE
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to proc Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. (2) 100' cement plug @ stub of production casing cut. <i>If</i> Ey,	io offset producers luce. will be used between all plugs. C Top & BIM. OF SHE
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. (2) 100' cement plug @ stub of production casing cut. (3) 100' cement plug @ surface casing shoe.	io offset producers luce. will be used between all plugs. C TOP & BIM. OF SAC Pose ()
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. (2) 100' cement plug @ stub of production casing cut. (3) 100' cement plug @ surface casing shoe.	io offset producers luce. will be used between all plugs. C TOP & BIM. OF SAC Pose ()
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. (2) 100' cement plug @ stub of production casing cut. (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker 4" dia., set in concrete w/4' above GL with lease	io offset producers luce. will be used between all plugs. C TOP & BIM. OF SAC Pose ()
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. (2) 100' cement plug @ stub of production casing cut. (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker 4" dia., set in concrete w/4' above GL with lease	io offset producers luce. will be used between all plugs. C TOP & BIM. OF SAC Pose ()
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prode Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. 100' pluce (2) 100' cement plug @ stub of production casing cut. 115 Gyr, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead to bottom, unit letter, section, township and range. 	to offset producers huce. will be used between all plugs. C TOP & BTM. OF SHE Mase name, well No.,
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prode Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. 100' pluce (2) 100' cement plug @ stub of production casing cut. 115 Gyr, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead to bottom, unit letter, section, township and range. 	co offset producers luce. will be used between all plugs. C TOP & BTM. OF SHE Mase name, well No.,
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. (2) 100' cement plug @ stub of production casing cut. (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker 4" dia., set in concrete w/4' above GL with lease	co offset producers luce. will be used between all plugs. C TOP & BTM. OF SHE Mase name, well No.,
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to proceed plugging procedure is as follows: Note-Mud laden fluid we (1) 100' cement plus @ bottom. 100' cement plug @ bottom. 100' cement plug @ stub of production casing cut. 116 Gyr, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead location, unit letter, section, township and range. Notice will be given when final cleanup has been made and location. 	co offset producers luce. will be used between all plugs. C TOP & BTM. OF SHE Mase name, well No.,
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prode Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. 100' pluce (2) 100' cement plug @ stub of production casing cut. 115 Gy, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with leadoration, unit letter, section, township and range. Notice will be given when final cleanup has been made and location Proposed plugging date is Dec., 1975. 	io offset producers huce. will be used between all plugs. (FOR & BIM. OF SAC POSCI) ase name, well No., n is ready for inspection.
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prode Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. 100' pluce (2) 100' cement plug @ stub of production casing cut. 115 Gy, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with leador to control of the section, township and range. Notice will be given when final cleanup has been made and location. Proposed plugging date is Dec., 1975. 	io offset producers huce. will be used between all plugs. (FOR & BIM. OF SAC POSCI) ase name, well No., n is ready for inspection.
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prode Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. 100' pluce (2) 100' cement plug @ stub of production casing cut. 115 Gy, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with leador to control of the section, township and range. Notice will be given when final cleanup has been made and location. Proposed plugging date is Dec., 1975. 	io offset producers huce. will be used between all plugs. (FOR & BIM. OF SAC POSCI) ase name, well No., n is ready for inspection.
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. 100' pluce (2) 100' cement plug @ stub of production casing cut. 115 Gy, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with leador to control of the section, township and range. Notice will be given when final cleanup has been made and location. Proposed plugging date is Dec., 1975. 	io offset producers huce. will be used between all plugs. (FOR & BIM. OF SAC POSCI) ase name, well No., n is ready for inspection.
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to proceed plugging procedure is as follows: Note-Mud laden fluid we (1) 100' cement plus @ bottom. (1) 100' cement plus @ bottom. (2) 100' cement plug @ stub of production casing cut. (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead location, unit letter, section, township and range. Notice will be given when final cleanup has been made and location.	io offset producers huce. will be used between all plugs. (FOR & BIM. OF SAC POSCI) ase name, well No., n is ready for inspection.
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prodeen proposed plugging procedure is as follows: Note-Mud laden fluid we (1) 100' cement plus @ bottom. 100' Pluce (2) 100' cement plug @ stub of production casing cut. 115 Gyr, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead location, unit letter, section, township and range. Notice will be given when final cleanup has been made and location. Proposed plugging date is Dec., 1975. THE Community Must BE MODER 24 (HBS PRIOR TOSEFT). THE Community formation above is true and complete to the best of my knowledge and beliet. 	no offset producers luce. will be used between all plugs. <i>C TOP & BTM. OF SHE</i> <i>POSC ()</i> ase name, well No., as ready for inspection. <i>NG BTM PLAC</i>
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. 100' pluce (2) 100' cement plug @ stub of production casing cut. 115 Gy, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with leador to control of the section, unit letter, section, township and range. Notice will be given when final cleanup has been made and location. Proposed plugging date is Dec., 1975. 	co offset producers huce. will be used between all plugs. <i>C TOP & BTM. OF SHE</i> <i>POSC ()</i> ase name, well No., n is ready for inspection. <i>NG BTM MAG</i>
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to proceed plugging procedure is as follows: Note-Mud laden fluid we (1) 100' cement plus @ bottom. 100' PLuce (2) 100' cement plug @ stub of production casing cut. 115 Gyr, (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead location, unit letter, section, township and range. Notice will be given when final cleanup has been made and location. Proposed plugging date is Dec., 1975. THE Commission MUST BE NOTHFICH LY HAS PRIOR TOSEFTY. 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. 	co offset producers huce. will be used between all plugs. <i>C TOP & BTM. OF SHE</i> <i>POSC ()</i> ase name, well No., n is ready for inspection. <i>NG STM PLAC</i>
 Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to proceed proposed plugging procedure is as follows: Note-Mud laden fluid we (1) 100' cement plus @ bottom. 100' pluce (2) 100' cement plug @ stub of production casing cut. 1/F 6/. (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead location, unit letter, section, township and range. Notice will be given when final cleanup has been made and location? Proposed plugging date is Dec., 1975. THE Commission Musical BE MOTHERS PRIOR TOSEFTICAL LY HAS PRIOR TOSEFTICAL. Stoned Dugging date is true and complete to the beast of my knowledge and belief. Stoned Dugging by the second production of the plug and complete to the beast of my knowledge and belief. 	co offset producers huce. will be used between all plugs. <i>C TOP & BTM. OF SHE</i> <i>POSC ()</i> ase name, well No., n is ready for inspection. <i>NG STM PLAC</i>
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prodere the proposed plugging procedure is as follows: Note-Mud laden fluid we (1) 100' cement plus @ bottom. 100' PLuce (2) 100' cement plug @ stub of production casing cut. 16 Synt (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead location, unit letter, section, township and range. Notice will be given when final cleanup has been made and location. THE Commansion Must BE WOITHER LY HAS PRIOR TOSEFTICATION. (4) Ibereby certify that the participan above is true and complete to the beat of my knowledge and belief. Signed by, Lis Chapting	co offset producers huce. will be used between all plugs. <i>C TOP & BTM. OF SHE</i> <i>POSC ()</i> ase name, well No., n is ready for inspection. <i>NG STM PLAC</i>
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prodered plugging procedure is as follows: Note-Mud laden fluid were the plug of the proposed plugging procedure is as follows: Note-Mud laden fluid were the plug of the proposed plugging description casing cut. (1) 100' cement plug @ bottom. (2) 100' cement plug @ stub of production casing cut. (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead location, unit letter, section, township and range. Notice will be given when final cleanup has been made and location. Proposed plugging date is Dec., 1975. THE Commansion MUST BE NOTHER LY HAS PRIOR TOSEFT, 18.1 hereby certify that the information above is true and complete to the best of my knowledge and belief. Signed by Lis Childrens	no offset producers luce. will be used between all plugs. <i>C TOP & BTM. OF SHE</i> <i>POSC ()</i> ase name, well No., as ready for inspection. <i>NG BTM PLAC</i>
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prode Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. 100' Pluce (2) 100' cement plug @ stub of production casing cut. 116 Synt (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead location, unit letter, section, township and range. Notice will be given when final cleanup has been made and location Proposed plugging date is Dec., 1975. THE Commission MUST BE NOTIFICE LY HES PRIOR TOSEFT. 1d. I hereby certify that the mormation above is true and complete to the best of my knowledge and belief. stoned Dird. Signed by Les Charactis Approvide ay Office Spring. 1000	co offset producers huce. will be used between all plugs. <i>C TOP & BTM. OF SHE</i> <i>POSC ()</i> ase name, well No., n is ready for inspection. <i>NG STM PLAC</i>
Temporarily abandoned in February of 1971. Request permission to plug and abandon Well No. 22-2 (W.I.) due to cutting high percentages of water, which is not economical to prod Proposed plugging procedure is as follows: Note-Mud laden fluid w (1) 100' cement plus @ bottom. (2) 100' cement plug @ stub of production casing cut. (3) 100' cement plug @ surface casing shoe. (4) 10sx cement plug @ surface. (5) Steel marker, 4" dia., set in concrete w/4' above GL with lead location, unit letter, section, township and range. Notice will be given when final cleanup has been made and location Proposed plugging date is Dec., 1975. THE Commentsion Music BE WINFIGH Ly HES PRIOR TOSEFT, 18. Thereby centify that the information above is true and complete to the best of my knowledge and belief. Store July Lis Chinema	co offset producers huce. will be used between all plugs. <i>C TOP & BTM. OF SHE</i> <i>POSC ()</i> ase name, well No., n is ready for inspection. <i>NG STM PLAC</i>

ſ

ŀ