NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOSSIG OFFICE OCC

MISCELLANEOUS REPORTS ON WELLS

1855 APR 25 FM 3:10

Submit this report in TRIPLICATE to the District Office, Oil Conservation Commission, within 10 days after the work specified is completed. It should be signed and filed as a report on Beginning Drilling Operations, Results of test of casing shut-off, result of plugging of well, result of well repair, and other important operations, even though the work was witnessed by an agent of the Commission. See additional instructions in the Rules and Regulations of the Commission.

	I	ndicate Nature of Report by Checking Be	low
REPORT ON BEGINNING DRILLING OPERATIONS		REPORT ON RESULT OF TEST OF CASING SHUT-OFF	REPORT ON REPAIRING WELL
REPORT ON RESULT DF PLUGGING WELL	x	REPORT ON RECOMPLETION OPERATION	REPORT ON (Other)
		April 22, 1955	Hobbs, New Maries
Following is a report on the	work done a	(= 410)	(Place)
		and the results obtained under the heading n	oted above at the
Oulf Cil Gor (Company	or Operator)		Chaves State "BS"
Los County	leading Pe	llere Well No.	in the 1/4 of Sec. 1
	tractor)		
, R, NMPM.	,	Pool,	Charves
he Dates of this work were as fold	ws:	April 17-20, 1955	
			,
otice of intention to do the work	(was) (submitted on Form C-102 on	(Cross out incorrect words)
d approval of the proposed plan	(was)	at) obtained.	
Di	ETAILED A	CCOUNT OF WORK DONE AND REST	TO ADDAINED
D	ETAILED A	CCOUNT OF WORK DONE AND RESUI	LTS OBTAINED
Plugged and abandoned			LTS OBTAINED
Plugged and abandoned 1. Ram 2-3/8" tub 2. Filled 5-1/2" 3. Spotted 10 sam h. Set h" x h' pi	well as sing to) saming to its comen pe marks	fellows: Ogh'. Spetted 10 sacks came: o surface with heavy mad. t from 25' to surface. F.	
Plugged and abandoned 1. Ram 2-3/8" tub 2. Filled 5-1/2" 3. Spotted 10 sam 4. Set h" x h' pi	well as sing to) saming to its comen pe marks	fellows: Ogh!. Spetted 10 sacks came: e surface with heavy mad. t from 25! to surface.	
Plugged and abandoned 1. Ram 2-3/8" tub 2. Filled 5-1/2" 3. Spotted 10 sam h. Set h" x h' pi //itnessed by	well as sing to) easing to its comen po marks:	Gulf Oil Carporation (Company) (Company)	Picial Portugal (Title)
Plugged and abandoned 1. Ram 2-3/8" tak 2. Filled 5-1/2" 3. Spotted 10 sam 4. Set k" x k' pi (Name of the content of the con	well as sing to) easing to its comen po marks:	Gulf Oil Corporation (Company) I hereby certify that to the best of my known is a second control of the control of the certify that to the best of my known is a second control of the certify that to the best of my known is a second control of the certify that to the best of my known is a second control of the certify that to the best of my known is a second control of the certify that to the best of my known is a second control of the certify that to the best of my known is a second control of the certify that to the best of my known is a second control of the certify that to the best of my known is a second control of the certify that the certification is a second control of the ce	Picial Porcess (Title)