FILE U.S.G.S. LAND OFFICE OPERATOR SLINDRY NOTICES AND	EXICO OIL CONSERVATION COMMISSION	Supersedes Old C-102 and C-103 Effective 1-1-65
FILE U.S.G.S. LAND OFFICE OPERATOR SLINDRY NOTICES AND	EXICO OIL CONSERVATION COMMISSION	
U.S.G.S. LAND OFFICE OPERATOR SLINDRY NOTICES AND		
OPERATOR SLINDRY NOTICES AND		
SLINDRY NOTICES AND		5a. Indicate Type of Lease
SLINDRY NOTICES AND		State Fee X
SUNDRY NOTICES AND		5. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS TOO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OF PLUG BACK TO A DIFFERENT RESERVOIR. JSE "APPLICATION FOR PERMIT _" (FOR A C-101) FOR SUCH PROPOSALS.) 1. GIL GAS		
		7. Unit Agreement Name
WELL WELL OTHER- WAT	er Injection	D. Q. S. U.
2. Name of Operator Cities Service Oil Company		8. Farm or Lease Name Tract 47
3. Address of Operator		9. Well No.
Box 69 - Hobbs, New Mexico		2
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER D ,	A THE NORTH LINE AND 660 FE	Caprock Queen
Use to 11	the are	
THE WEST LINE, SECTION T	CHASHIR 148 RANGE 31E	_NMPM.
15. Elevar	ti: z (Si ow whether DF, RT, GR, etc.)	12. County
	4410 DF	Chaves ()
Check Appropriate Box	To Indicate Nature of Notice, Report	or Other Data
NOTICE OF INTENTION TO:		QUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG	S AND ASANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING CHAN	G: PLA .S CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
 Describe Froposed of Completed Operations (Clearly statement) SEE RULE 1103. 	te all pertinent details, and give pertinent dates, in	cluding estimated date of starting any proposed
We porpose to plug and abandon 1. Set CI bridge plug in car 2. Set 25 sack cement plug 3. Load hole with mud laden	on the above well in the follow sing just above open hole (7" on top of bridge plug. fluid. ce plug with a 4" dry hole mar	ing manner: set @ 3046 w/125 sacks)
We porpose to plug and abandon 1. Set CI bridge plug in car 2. Set 25 sack cement plug 3. Load hole with mud laden 4. Set 10 sack cement surface 5. Clean location of all decorated	sing just above open hole (7" son top of bridge plug. fluid. ce plug with a 4" dry hole mar. bris and equipment.	ing manner: set @ 3046 w/125 sack#) ker.
We porpose to plug and abandoni. Set CI bridge plug in care. 2. Set 25 sack cament plug and abandonic set 25 sack cament plug and abandonic set 25 sack cament plug and abandonic set 25 sack cament surface. Set 10 sack cament surface. 5. Clean location of all decided set 25 sack cament surface.	on the above well in the follow sing just above open hole (7" on top of bridge plug. fluid. ce plug with a 4" dry hole mark bris and equipment.	ing manner: set @ 3046 w/125 sack#) ker.

RECITO

.

. :

MAY 2 1 15 TM

.

OIL CONSTRUCTION DEM.