OF COPIES RECEIVED	1	Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
AFE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.	1	5a. Indicate Type of Lease
LAND OFFICE	1	State X Fee.
OPERATOR	1	5. State Oil & Gas Lease No.
OFERA, OR	J	
CINDE	W NOTICES AND DEPORTS ON WELLS	
	RY NOTICES AND REPORTS ON WELLS OPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. FION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	7, Unit Agreement Name
OIL GAS WELL WELL	OTHER- Water Injection	Eastcap Queen
2. Name of Operator Miller & Miller Au	ctioneers, Inc.	
3. Address of Operator		9. Well No.
		33
4. Location of Well		10. Field and Pool, or Wildcat
	660 FEET FROM THE SOUTH LINE AND 1980 FEET	Caprock Queen
UNIT LETTER	FEET FROM THE SOUCH LINE AND 1900 PEET	
East LINE, SECTION	34 TOWNSHIP 14 South RANGE 31 East	WMPM. (())
		12. County
	15. Elevation (Show whether DF, RT, GR, etc.)	Chaves
16. Chack	Appropriate Box To Indicate Nature of Notice, Report o	or Other Data
	• • · ·	JENT REPORT OF:
	E	,
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JQB	_
	OTHER	
OTHER		
17 Describe Proposed or Completed O	perations (Clearly state all pertinent details, and give pertinent dates, incl	luding estimated date of starting any proposed
work) SEE RULE 1103.		
	•	
n.1	Set bridge plug above 3092' and cap	
Plugging Program:	Ser bringe billo above 3032 and Cab	with 35! domont
	bet silage play asets the same D	with 35' cement.
•	Mud hole. Cut off $5-1/2$ " casing. P	lace 100' cement
,	Mud hole. Cut off $5-1/2$ " casing. P plug at top of stub. If stub is bel	lace 100' cement ow top of salt,
,	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal	lace 100' cement ow top of salt, t. Place 100'
	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap
,	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs
,	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs
	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs
	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs
	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs
	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil start of operations. before Setting	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs ng botton plug.
	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil start of operations. before Setting	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs ng botton plug.
All Cement	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil start of operations. before Setting	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs ng botton plug.
All Cement	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs ng botton plug.
All Cement	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil start of operations. before Setting	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs ng botton plug.
All Cement	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil start of operations. before Setting	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs ng botton plug.
	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8- with 10 sacks of cement. Notify Oil start of operations. before Setting ### Plugs Must be spatial.	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs ng botton plug.
	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8-with 10 sacks of cement. Notify Oil start of operations. before Setting	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission ** 24 hrs ng botton plug.
18. I hereby certify that the information	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8- with 10 sacks of cement. Notify Oil start of operations. before Setting h above is true and complete to the best of my knowledge and belief.	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission at 24 hrs ing botton plug.
18. I hereby certify that the information	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8- with 10 sacks of cement. Notify Oil start of operations. before Setting h above is true and complete to the best of my knowledge and belief.	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission at 24 hrs ing botton plug.
18. I hereby certify that the information	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8- with 10 sacks of cement. Notify Oil start of operations. before Setting ### Plugs Must be spatial.	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission at 24 hrs ing botton plug.
18. I hereby certify that the information	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8- with 10 sacks of cement. Notify Oil start of operations. before Setting n above is true and complete to the best of my knowledge and belief.	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission at 24 hrs ing botton plug.
18. I hereby certify that the information	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8- with 10 sacks of cement. Notify Oil start of operations. before Setting n above is true and complete to the best of my knowledge and belief.	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission at 24 hrs ing botton plug.
18. I hereby certify that the information	Mud hole. Cut off 5-1/2" casing. P plug at top of stub. If stub is bel place 100' cement plug at top of sal cement plug to straddle bottom of 8- with 10 sacks of cement. Notify Oil start of operations. before Setting n above is true and complete to the best of my knowledge and belief. TITLE VICE PREMICE. TITLE VICE PREMICE.	lace 100' cement ow top of salt, t. Place 100' 5/8" casing. Cap Commission at 24 hrs ing botton plug.