

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>	5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
Name of Operator <i>Gandy Corp. M.C. Gandy & Dale Gandy</i>			5. State Oil & Gas Lease No.
Address of Operator 1109 E. Broadway, Tatum, NM 88267			7. Unit Agreement Name
Location of Well UNIT LETTER <u>C</u> 1980 FEET FROM THE <u>West</u> LINE AND <u>660'</u> FEET FROM THE <u>North</u> LINE, SECTION <u>9</u> TOWNSHIP <u>8-S</u> RANGE <u>33-E</u> NMPM.			8. Farm or Lease Name Annie Davis
			9. Well No. 1
			10. Field and Pool, or Wildcat Chaveroo - <u>SA</u>
15. Elevation (Show whether DF, RT, GR, etc.)			12. County Chavez

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

FORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
LEAK OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Propose to P&A well in the following manner:

1. MIRU POH w/rods, pump & tubing.
2. GIH w/tbg. OE (4250) spot 25 sx 4250' to 3900' P.T. to approx. 400'-500') WOC 4-5 hrs.
3. GIH w/tbg. tag plug
Circ hole w/9.5 # /gal BW cont'g bbl gel
POH w/tbg.
4. Perf. 4½ cas 4 shots (50') below 8 5/8 Csg. Shoe.
5. Pump 100 Sx plug 90 sx IF, leave 10 sz in 4½ csg.
6. 10 sx plug at surf.
7. Cut off WH. Install regulation dry hole marker.
Clean and level location for abandonement.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

BY *H. G. Starling* TITLE H. G. STARLING, CONSULTANT

DATE 2-28-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR

TITLE

DATE FEB 28 1986

CONDITIONS OF APPROVAL, IF ANY: