	_						
NO. OF COPIES RECEIVED]			Form C-103			
DISTRIBUTION				Supersedes Ol			
SANTA FE	NEW MEXICO OIL CONS	ERVATION COMMISSION		C-102 and C-1 Effective 1-1-6			
FILE]				-		
U.S.G.S.]			5a. Indicate Type	of Lease		
LAND OFFICE]			State X	Fee,		
OPERATOR				5. State Oil & Gas	: Lease No.		
	-			OG	1195		
DO NOT USE THIS FORM FOR PRO	RY NOTICES AND REPORTS ON OF POSALS TO DRILL OR TO DEEPEN OR PLUG B.	WELLS ACK TO A DIFFERENT RESERVOIP H PROPOSALS.)					
1	N <u>e we and that in a standard of a standard and a</u>			7. Unit Agreement	Name		
OIL SAS WELL	OTHER-						
2. Name of Operator				8. Farm or Lease Name			
Atlantic Richfield Company					State BF		
3. Address of Operator				9. Well No.			
P. O. Box 1710, Hol	bbs, New Mexico 88240			5			
					10. Field and Pool, or Wildcat		
	330 FEET FROM THE North	990	FEET FROM	Chaveroo-	San Andres		
				<u>uuuuuu</u>	<u>IIIIIIIII</u>		
THE West LINE SECTION	ON TOWNSHIP 85	BANGE 33E	NMPM.				
		BOOVE	A @ F M .				
	15. Elevation (Show whether	DF, RT, GR, etc.)		12. County	VIIIIII		
	441	15'DF		Chaves			
^{16.} Check	Appropriate Box To Indicate N	ature of Notice. Repo	rt or Oth	er Data			
	NTENTION TO:	•		REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK		ALTERI	NG CASING		
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.		PLUG AN	ID ABANDONMENT		
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOE					
		OTHER Shut in.	Tempora	arily Abando	ned X		
OTHER							

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The above well was shut in&temporarily abandoned November 10, 1966. The well was shut in and abandoned because it was uneconomical to produce. There are no recompletion possibilities for this well. The well is to be P&A in accordance w/OCC approval dated June 21, 1974. Work to commence no later than 1st quarter 1975.

Jure 10/1/25

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGHED		TITLE Dist.	Prod. & Drlg.	Supt.	DATE_	October	31,	1974
APPROVED BY	Orig. Signed by Joe D. Ramey Historic Super-	TITLE			DATE			



Job separation sheet

.

·

DISTRIBUTION		Form C-103 Supersedes Old
	NEW MEXICO OU CONSEDUATION COMMISSION	C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
		5a. Indicate Type of Lease
U.S.G.S.		State X Fee
		5. State Oil & Gas Lease No.
OPERATOR		OG 1195
SUNDO		k
JUNDA (Do not use this form for pro- use "applicati	Y NOTICES AND REPORTS ON WELLS prosals to drill or to deepen or plug back to a different reservoir. ion for permit (form C-101) for such proposals.)	
OIL X GAS WELL	OTHER-	
Atlantic Richfield Com	npany	8. Form or Lease Name State BF
. Address of Operator		9. Well No.
P. O. Box 1710, Hobbs,	New Mexico 88240	5
Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER D 3	330 FEET FROM THE North LINE AND 990	Chaveroo-San Andres
	ON 3 TOWNSHIP 85 RANGE 33E	
TRE LINE, SECTIO		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4415' DF	Chaves ()))))
6. Check	Appropriate Box To Indicate Nature of Notice, Repor	t or Other Data
		EQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND CEMENT JOB	
	OTHER	
OTHER		
	perations (Clearly state all pertinent details, and give pertinent dates,	including estimated date of starting any propose
17. Describe Proposed or Completed Op work) SEE RULE 1103.	perations (Clearly state all pertinent details, and give pertinent dates,	including estimated date of starting any propose
work) SEE RULE 1903.		including estimated date of starting any propose
work) SEE RULE 1103. Present TD 4500', PBD	4412'. Well was TA on 11/10/66.	including estimated date of starting any propose
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c	4412'. Well was TA on 11/10/66. cmtd w/255 sx. Cmt circ to surface.	including estimated date of starting any propose
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4 ¹ / ₂ " OD csg @ 4499' cmt	4412'. Well was TA on 11/10/66. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'.	including estimated date of starting any propose
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4 ¹ / ₂ " OD csg @ 4499' cmt Present perforations 4	4412'. Well was TA on 11/10/66. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'.	including estimated date of starting any propose
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll	4412'. Well was TA on 11/10/66. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows:	including estimated date of starting any propose
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417	4412'. Well was TA on 11/10/66. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'.	including estimated date of starting any propose
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4 ¹ / ₂ " OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4 ¹ / ₂ " csg @ free poi	4412'. Well was TA on 11/10/66. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull.	including estimated date of starting any propose
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub.	including estimated date of starting any propose
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4 ¹ / ₂ " OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4 ¹ / ₂ " csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross 8-5/8" csg shoe 300-447'.	·
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross $8-5/8$ " csg shoe 300-447'. surface. Heavy mud-laden material to be pi	laced between plugs.
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross $8-5/8$ " csg shoe 300-447'. surface. Heavy mud-laden material to be properties. rker, level & clean location. Your office	laced between plugs.
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross $8-5/8$ " csg shoe 300-447'. surface. Heavy mud-laden material to be properties. rker, level & clean location. Your office	laced between plugs.
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross $8-5/8$ " csg shoe 300-447'. surface. Heavy mud-laden material to be pinker, level & clean location. Your office spection.	laced between plugs. to be notified when location
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross $8-5/8$ " csg shoe 300-447'. surface. Heavy mud-laden material to be pinker, level & clean location. Your office spection. THE COM.	laced between plugs. to be notified when location MISSION MUST BE NOTIFIED 24
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross 8-5/8" csg shoe 300-447'. surface. Heavy mud-laden material to be pinker, level & clean location. Your office spection. THE COMM	laced between plugs. to be notified when location MISSION MUST BE NOTIFIED 24 RIOR TO THE BEGINNING OF
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross 8-5/8" csg shoe 300-447'. surface. Heavy mud-laden material to be provide the second s	laced between plugs. to be notified when location MISSION MUST BE NOTIFIED 24 RIOR TO THE BEGINNING OF G OPERATIONS FOR THE C-103
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross 8-5/8" csg shoe 300-447'. surface. Heavy mud-laden material to be pinker, level & clean location. Your office spection. THE COMM	laced between plugs. to be notified when location MISSION MUST BE NOTIFIED 24 RIOR TO THE BEGINNING OF G OPERATIONS FOR THE C-103
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar is ready for final ins	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross $8-5/8$ " csg shoe 300-447'. surface. Heavy mud-laden material to be pl rker, level & clean location. Your office spection. THE COM. HOURS PI PLUGGING TO BE AP	laced between plugs. to be notified when location MISSION MUST BE NOTIFIED 24 RIOR TO THE BEGINNING OF G OPERATIONS FOR THE C-103
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar is ready for final ins	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross 8-5/8" csg shoe 300-447'. surface. Heavy mud-laden material to be provide the second s	laced between plugs. to be notified when location MISSION MUST BE NOTIFIED 24 RIOR TO THE BEGINNING OF G OPERATIONS FOR THE C-103
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar is ready for final ins	4412'. Well was TA on 11/10/66. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. Hows: 71-4390'. int & pull. ross 4½" csg stub. ross 8-5/8" csg shoe 300-447'. surface. Heavy mud-laden material to be plant rker, level & clean location. Your office spection. THE COM. HOURS PA PLUGGING TO BE AP	laced between plugs. to be notified when location MISSION MUST BE NOTIFIED 24 RIOR TO THE BEGINNING OF G OPERATIONS FOR THE C-103
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar is ready for final ins	4412'. Well was TA on $11/10/66$. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. lows: 71-4390'. int & pull. ross $4\frac{1}{2}$ " csg stub. ross $8-5/8$ " csg shoe 300-447'. surface. Heavy mud-laden material to be pl rker, level & clean location. Your office spection. THE COM. HOURS PI PLUGGING TO BE AP	laced between plugs. to be notified when location MISSION MUST BE NOTIFIED 24 RIOR TO THE BEGINNING OF G OPERATIONS FOR THE C-103 PROVED.
work) SEE RULE 1103. Present TD 4500', PBD 8-5/8" OD csg @ 376' c 4½" OD csg @ 4499' cmt Present perforations 4 Propose to P&A as foll Set 20 sk cmt plug 417 Cut 4½" csg @ free poi Set 40 sk cmt plug acr Set 50 sk cmt plug acr Set 10 sk cmt plug @ s Install regulation mar is ready for final ins	4412'. Well was TA on 11/10/66. cmtd w/255 sx. Cmt circ to surface. td w/300 sx. TOC behind csg @ 3211'. 4225-4390'. Hows: 71-4390'. int & pull. ross 4½" csg stub. ross 8-5/8" csg shoe 300-447'. surface. Heavy mud-laden material to be plant rker, level & clean location. Your office spection. THE COM. HOURS PA PLUGGING TO BE AP	laced between plugs. to be notified when location MISSION MUST BE NOTIFIED 24 RIOR TO THE BEGINNING OF G OPERATIONS FOR THE C-103 PROVED.

CONDITIONS	OF	APPROVAL,	١F	ANY