	~	· .	N	
		1.00		

•

	Form Approved. Budget Bureau No. 42–R1424
UNITED STATES	5. LEASE
DEPARTMENT OF THE INTERIOR	NM-044628 NM-0444 128
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME
SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)	
1. oil gas	8. FARM OR LEASE NAME Cato "C" Federal
well well other	9. WELL NO.
2. NAME OF OPERATOR AMOCO PRODUCTION COMPANY	1 10. FIELD OR WILDCAT NAME
3. ADDRESS OF OPERATOR P.O. Drawer "A" Levelland, TX 79336	Cato-San Andres
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
below.)	14-8-30
AT SURFACE: 1980'FSL&1980FEL, Sec.4 (Unit), AT TOP PROD. INTERVAL: AT TOTAL DEPTH: NW ¹ ₄ , SW ¹ ₄)	12. COUNTY OR PARISH 13. STATE Chaves NM
6. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:	4158-RDB
TEST WATER SHUT-OFF	
FRACTURE TREAT	
	(NOTE: Report results of multiple completion or zone
PULL OR ALTER CASING	change on Form 9-330.)
AULTIPLE COMPLETE	한 방상 승규는 것 같아요. 같이 나는 것 같아요. 나는 것 같아요.
ABANDON*	
other)	· · · · · · · · · · · · · · · · · · ·
	irectionally utilied, give subsurface locations and
measured and true vertical depths for all markers and zones pertiner Propose to increase production by the following 3570' and clear hole to 3655'. Perforate 3580- packer. Acidize with 3000 gal. 20% LSTNE acid. bridge plug at appx. 3560' and set packer at ap Return well to production.	procedure. Drill out cement retai 3628' with 2 DJSPF. Run tubing and Pull tubing and packer. Set ret.
Propose to increase production by the following 3570' and clear hole to 3655'. Perforate 3580- packer. Acidize with 3000 gal. 20% LSTNE acid. bridge plug at appx. 3560' and set packer at ap	nt to this work)* procedure. Drill out cement retai 3628' with 2 DJSPF. Run tubing and Pull tubing and packer. Set ret.
Propose to increase production by the following 3570' and clear hole to 3655'. Perforate 3580- packer. Acidize with 3000 gal. 20% LSTNE acid. bridge plug at appx. 3560' and set packer at ap Return well to production.	nt to this work)* procedure. Drill out cement retai 3628' with 2 DJSPF. Run tubing and Pull tubing and packer. Set ret.
Propose to increase production by the following 3570' and clear hole to 3655'. Perforate 3580- packer. Acidize with 3000 gal. 20% LSTNE acid. bridge plug at appx. 3560' and set packer at ap Return well to production.	nt to this work)* procedure. Drill out cement retai 3628' with 2 DJSPF. Run tubing and Pull tubing and packer. Set ret.
Propose to increase production by the following 3570' and clear hole to 3655'. Perforate 3580- packer. Acidize with 3000 gal. 20% LSTNE acid. bridge plug at appx. 3560' and set packer at ap Return well to production.	nt to this work.)* procedure. Drill out cement retai 3628' with 2 DJSPF. Run tubing and Pull tubing and packer. Set ret. px.2470'. Acidize with 1500 gal ac Set @Ft.
Propose to increase production by the following 3570' and clear hole to 3655'. Perforate 3580- packer. Acidize with 3000 gal. 20% LSTNE acid. bridge plug at appx. 3560' and set packer at ap Return well to production.	nt to this work.)* procedure. Drill out cement retai 3628' with 2 DJSPF. Run tubing and Pull tubing and packer. Set ret. px.2470'. Acidize with 1500 gal ac Set @Ft.
Propose to increase production by the following 3570' and clear hole to 3655'. Perforate 3580- packer. Acidize with 3000 gal. 20% LSTNE acid. bridge plug at appx. 3560' and set packer at ap Return well to production. Beturn well to production.	<pre>nt to this work.)* procedure. Drill out cement retai 3628' with 2 DJSPF. Run tubing and Pull tubing and packer. Set ret. px.2470'. Acidize with 1500 gal ac Set @Ft. nalyst_re10-24-78 </pre>
Propose to increase production by the following 3570' and clear hole to 3655'. Perforate 3580- packer. Acidize with 3000 gal. 20% LSTNE acid. bridge plug at appx. 3560' and set packer at ap Return well to production. Subsurface Safety Valve: Manu. and Type Return well to production. B. I hereby certify that the foregoing is true and correct signed Memory Warry TITLE Asst. Admn. A PPPROVED BY (This space for Federal or State offic CONDITIONS OF APPROVAL, IF ANT: 0+4 - USGS-A	<pre>nt to this work.)* procedure. Drill out cement retai 3628' with 2 DJSPF. Run tubing and Pull tubing and packer. Set ret. px.2470'. Acidize with 1500 gal ac Set @Ft. nalyst_re10-24-78 </pre>
Propose to increase production by the following 3570' and clear hole to 3655'. Perforate 3580- packer. Acidize with 3000 gal. 20% LSTNE acid. bridge plug at appx. 3560' and set packer at ap Return well to production. Subsurface Safety Valve: Manu. and Type Return well to production. B. I hereby certify that the foregoing is true and correct SIGNED	<pre>nt to this work.)* procedure. Drill out cement retai 3628' with 2 DJSPF. Run tubing and Pull tubing and packer. Set ret. px.2470'. Acidize with 1500 gal ac Set @Ft. nalyst_re10-24-78 </pre>

RECEIVED OCT 31 1978 ARTESIA, DFFICE

Lil CONSEQUE 6 1378