

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUL 29 8 39 AM '68

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-3259

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sun Oil Company	8. Farm or Lease Name New Mexico "H" State
3. Address of Operator P. O. Box 2792, Odessa, Texas 79760	9. Well No. 4
4. Location of Well UNIT LETTER D , 660 FEET FROM THE North LINE AND 660 FEET FROM THE West LINE, SECTION 16 TOWNSHIP 8 S RANGE 30 E N.M.P.M.	10. Field and Pool, or Wildcat Cato-San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4104' Gr.	12. Charles Cato-San

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input checked="" type="checkbox"/> Perforate and treat	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull rods, pump and tubing; perforate 4½" casing by Densilog measurements in Milnesand Zone at 3243', 46', 46', 56', 58', 60, 62', 64', 66', 70', 72', 74', 76', 83', 85' (15 holes) Acidize with 15% NE HCL acid(1500 gals.) and flush with fresh treated water. Acidize with 7500 gals 28% NE HCL and overflush with 7500 gals. treated fresh water. Test and rerun rods, pump and tubing.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED P. E. Happel	TITLE Area Engineer	DATE 7-26-68
APPROVED BY [Signature]	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		