(May 1963)	DEPARTMEN	ITED STAT		SUBMIT IN TRIPI (Other instructions	re	Form app Budget F	Bureau No. 42-
·		LOGICAL SL		(rende side)		NM 01554	
					6.	IF INDIAN, ALLO	
	RY NOTICE: rm for proposals t Jse "APPLICATIO:			WELLS to a different reservosi sals.)	r.		
I. OIL X GAS OTHER						7. UNIT AGREEMENT NAME	
2. NAME OF OPEBATOR					8	8. FARM OR LEASE NAME	
Atlantic Richf	ield Compan	ny		·	·	Winkler F	ederal
3. ADDRESS OF OPERATOR		ew Morrise (00040		9.	WELL NO.	
P. O. Box 1710, Hobbs, New Mexico 88240 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*						13 10. FIELD AND POOL, OR WILDCAT	
See also space 17 below.) At surface						Cato San Andres	
						1. SEC., T., B., M., SURVEY OR	OR BLK. AND
990' FNL & 165	0' FEL (Un:	it Letter 1	В)			·	
14						29-T8S-R	
14. PERMIT NO.	15	5. ELEVATIONS (Sho		GR, etc.)	1	2. COUNTY OB PA	
		41	15' GR			Chaves	N.M.
16.	Check Appro	priate Box To	Indicate Natu	re of Notice, Repa	ort, or Oth	er Data	
NOT	CICE OF INTENTION	то :			SUBSEQUENT	REPORT OF:	
TEST WATER SHUT-OFF	PULL	OR ALTER CASING		WATER SHUT-OFF		REPAIRI	ING WELL
FRACTURE TREAT	MULT	IPLE COMPLETE		FRACTURE TREATMES	NT	ALTERIN	NG CASING
SHOOT OR ACIDIZE	ABANI			SHOOTING OR ACIDIZ	BING	ABANDO	NMENT*
REPAIR WELL (Other)	Plug & Aba	GE PLANS	X	(Other) (Note: Report	t_results of	multiple complet	tion on Well
17. DESCRIBE PROPOSED OR CO proposed work. If w						on Report and Lo	
nent to this work.)* This well was or exist above pres TD 3530', PBD 34 8-5/8" OD 20# cs 4½" OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr	oducing 100 ent pay in 91'. Prese sg set @ 288 set @ 3530 as follows: 11 BOP & pa	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, p	hen shut i 3289-3321' w/200 sx. /300 sx.	n on 8/31/75. & 3352-3368" Circulated t TOC @ 2250'.	No otl	her zones	
This well was presented by the second secon	oducing 100 ent pay in 91'. Prese sg set @ 288 set @ 3530 as follows: 11 BOP & put taper to 328 etr on tbg perfs 3289-3 top. top. as indica	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, p 50', . Set reth 3368' thru etween all ated from b	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point	n on 8/31/75. & 3352-3368" Circulated t TOC @ 2250'. sx Cl C w/4% @ approx 2256	No ot o surfac gel. 1 0' & pu	her zones ce. Pull out o	of inter
This well was pre- exist above press TD 3530', PBD 34 8-5/8" OD 20# cs $4\frac{1}{2}$ " OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run $4\frac{1}{2}$ " cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut $4\frac{1}{2}$ " OD cs 7. Spot 35 sx Cl 8. Spot 35 sx Cl	oducing 100 ent pay in 91'. Press as set @ 288 set @ 3530 as follows: 11 BOP & pu- paper to 328 etr on tbg berfs 3289-3 top. top. as indica c w/4% get	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, y 50'. . Set retu 3368' thru etween all ated from 1 1 (100' plu 1 (100' plu	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10	n on 8/31/75. & 3352-3368" Circulated t TOC @ 2250'. sx Cl C w/4% @ approx 225% 4 ¹ /" OD csg s 50' across to	No ot o surfac gel. 1 0' & pu tub p of sa	her zones ce. Pull out o ll. lt @ 1000'	of inter
This well was pre- exist above press TD 3530', PBD 34 8-5/8" OD 20# cs $4\frac{1}{2}$ " OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run $4\frac{1}{2}$ " cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut $4\frac{1}{2}$ " OD cs 7. Spot 35 sx Cl 9. Spot 35 sx Cl	voducing 100 sent pay in 91'. Press as set @ 288 set @ 3530 as follows: 11 BOP & pu- paper to 328 etr on tbg berfs 3289-3 top. top. as indica C w/4% gen C w/4% gen	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, y 50'. . Set retu 3368' thru etween all ated from f 1 (100' plu 1 (100' plu 1 (100') in	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10 n & out of	n on 8/31/75. & 3352-3368" Circulated to TOC @ 2250'. sx Cl C w/4% @ approx 2256 4 ¹ /2" OD csg so 50' across to 8-5/8" csg so	No ot o surfac gel. 1 0' & pu tub p of sa hoe @ 28	her zones ce. Pull out o 11. 1t @ 1000' 38'.	of inter f retr &
This well was pre- exist above press TD 3530', PBD 34 8-5/8" OD 20# cs $4\frac{1}{2}$ " OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run $4\frac{1}{2}$ " cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut $4\frac{1}{2}$ " OD cs 7. Spot 35 sx Cl 8. Spot 35 sx Cl	voducing 100 sent pay in 91'. Press as set @ 288 set @ 3530 as follows: 11 BOP & pu- paper to 328 etr on tbg berfs 3289-3 top. top. as indica C w/4% gen C w/4% gen	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, y 50'. . Set retu 3368' thru etween all ated from f 1 (100' plu 1 (100' plu 1 (100') in	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10 n & out of	n on 8/31/75. & 3352-3368" Circulated to TOC @ 2250'. sx Cl C w/4% @ approx 2256 4 ¹ /2" OD csg so 50' across to 8-5/8" csg so	No ot o surfac gel. 1 0' & pu tub p of sa hoe @ 28	her zones ce. Pull out o 11. 1t @ 1000' 38'.	of inter f retr &
This well was pre- exist above press TD 3530', PBD 34 8-5/8" OD 20# cs $4\frac{1}{2}$ " OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run $4\frac{1}{2}$ " cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut $4\frac{1}{2}$ " OD cs 7. Spot 35 sx Cl 9. Spot 35 sx Cl	voducing 100 sent pay in 91'. Press as set @ 288 set @ 3530 as follows: 11 BOP & pu- paper to 328 etr on tbg berfs 3289-3 top. top. as indica C w/4% gen C w/4% gen	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, y 50'. . Set retu 3368' thru etween all ated from f 1 (100' plu 1 (100' plu 1 (100') in	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10 n & out of	n on 8/31/75. & 3352-3368" Circulated to TOC @ 2250'. sx Cl C w/4% @ approx 2256 4 ¹ /2" OD csg so 50' across to 8-5/8" csg so	No ot o surfac gel. 1 0' & pu tub p of sa hoe @ 28	her zones ce. Pull out o 11. 1t @ 1000' 38'.	of inter f retr &
This well was pre- exist above press TD 3530', PBD 34 8-5/8" OD 20# cs $4\frac{1}{2}$ " OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run $4\frac{1}{2}$ " cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut $4\frac{1}{2}$ " OD cs 7. Spot 35 sx Cl 9. Spot 35 sx Cl	voducing 100 sent pay in 91'. Press as set @ 288 set @ 3530 as follows: 11 BOP & pu- paper to 328 etr on tbg berfs 3289-3 top. top. as indica C w/4% gen C w/4% gen	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, y 50'. . Set retu 3368' thru etween all ated from f 1 (100' plu 1 (100' plu 1 (100') in	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10 n & out of	n on 8/31/75. & 3352-3368" Circulated to TOC @ 2250'. sx Cl C w/4% @ approx 2256 4 ¹ /2" OD csg so 50' across to 8-5/8" csg so	No ot o surfac gel. 1 0' & pu tub p of sa hoe @ 28	her zones ce. Pull out o 11. 1t @ 1000' 38'.	of inter f retr &
This well was pre- exist above press TD 3530', PBD 34 8-5/8" OD 20# cs $4\frac{1}{2}$ " OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run $4\frac{1}{2}$ " cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut $4\frac{1}{2}$ " OD cs 7. Spot 35 sx Cl 9. Spot 35 sx Cl	voducing 100 sent pay in 91'. Press as set @ 288 set @ 3530 as follows: 11 BOP & pu- paper to 328 etr on tbg berfs 3289-3 top. top. as indica C w/4% gen C w/4% gen	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, y 50'. . Set retu 3368' thru etween all ated from f 1 (100' plu 1 (100' plu 1 (100') in	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10 n & out of	n on 8/31/75. & 3352-3368" Circulated to TOC @ 2250'. sx Cl C w/4% @ approx 2256 4 ¹ /2" OD csg so 50' across to 8-5/8" csg so	No ot o surfac gel. 1 0' & pu tub p of sa hoe @ 28	her zones ce. Pull out o 11. 1t @ 1000' 38'.	of inter f retr &
This well was pre- exist above press TD 3530', PBD 34 8-5/8" OD 20# cs $4\frac{1}{2}$ " OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run $4\frac{1}{2}$ " cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut $4\frac{1}{2}$ " OD cs 7. Spot 35 sx Cl 9. Spot 35 sx Cl	oducing 100 sent pay in 91'. Press sg set @ 288 set @ 3530 as follows: 11 BOP & pu- paper to 328 etr on tbg berfs 3289-3 top. top. ag as indica C w/4% gen C w/4% gen C w/4% gen C w/4% gen	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, y 50'. . Set retu 3368' thru etween all ated from f 1 (100' plu 1 (100' plu 1 (100') in e, erect re	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10 n & out of	n on 8/31/75. & 3352-3368" Circulated to TOC @ 2250'. sx Cl C w/4% @ approx 2256 4 ¹ /2" OD csg so 50' across to 8-5/8" csg so	No ot o surfac gel. 1 0' & pu tub p of sa hoe @ 28	her zones ce. Pull out o 11. 1t @ 1000' 38'.	of inter f retr &
This well was prest exist above prest TD 3530', PBD 34 8-5/8" OD 20# cs $4\frac{1}{2}$ " OD 9.5# csg Propose to P&A at 1. Rig up, insta 2. Run bit & scr 3. Run $4\frac{1}{2}$ " cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut $4\frac{1}{2}$ " OD cs 7. Spot 35 sx Cl 8. Spot 35 sx Cl 9. Spot 35 sx cn 10. Spot 10 sx cm	oducing 100 sent pay in 91'. Press sg set @ 288 set @ 3530 as follows: 11 BOP & pu- paper to 328 etr on tbg berfs 3289-3 top. top. ag as indica C w/4% gen C w/4% gen C w/4% gen C w/4% gen	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, p 50'. . Set reth 3368' thru etween all ated from b 1 (100' ph 1 (100' ph 1 (100') in e, erect re	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10 n & out of egulation	n on 8/31/75. & 3352-3368" Circulated to TOC @ 2250'. sx Cl C w/4% @ approx 2256 4 ¹ /2" OD csg so 50' across to 8-5/8" csg so	No oth o surface gel. 1 0'& pul tub p of sa hoe @ 28 er, clea	her zones ce. Pull out o ll. lt @ 1000' 88'. an & level	of inter f retr &
This well was pre- exist above pres TD 3530', PBD 34 8-5/8" OD 20# cs 4½" OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run 4½" cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut 4½" OD cs 7. Spot 35 sx Cl 8. Spot 35 sx Cl 9. Spot 35 sx Cl 10. Spot 10 sx cm	ent pay in ent pay in 91'. Press g set @ 288 set @ 3530 as follows: 11 BOP & pu- perfs 3289-3 top. 10 c w/4% gel C w/4% gel	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, p 50'. . Set reth 3368' thru etween all ated from f 1 (100' ph 1 (100' ph 1 (100') in e, erect re	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10 n & out of egulation	n on 8/31/75. & 3352-3368" Circulated t TOC @ 2250'. sx Cl C w/4% @ approx 225% 4 ¹ '' OD csg ss 50' across tow 8-5/8" csg ss dry hole marka	No oth o surface gel. 1 0'& pul tub p of sa hoe @ 28 er, clea	her zones ce. Pull out o ll. lt @ 1000' 88'. an & level	of inter f retr & location
This well was prest exist above press TD 3530', PBD 34 8-5/8" OD 20# cs 4 ¹ / ₂ " OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run 4 ¹ / ₂ " cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut 4 ¹ / ₂ " OD cs 7. Spot 35 sx Cl 8. Spot 35 sx Cl 9. Spot 35 sx Cl 10. Spot 10 sx cm	ent pay in ent pay in 91'. Press g set @ 288 set @ 3530 as follows: 11 BOP & pu- perfs 3289-3 top. 10 c w/4% gel C w/4% gel	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, p 50', . Set reth 3368' thru etween all ated from t 1 (100' plu 1 (100') in e, erect re e and correct	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10 n & out of egulation	n on 8/31/75. & 3352-3368" Circulated t TOC @ 2250'. sx Cl C w/4% @ approx 225% 4 ¹ '' OD csg ss 50' across tow 8-5/8" csg ss dry hole marka	No oth o surface gel. 1 0'& put tub p of sa hoe @ 28 er, clea	her zones ce. Pull out o ll. lt @ 1000' 88'. an & level DATE	of inter f retr & location
This well was prest exist above prest TD 3530', PBD 34 8-5/8" OD 20# cs 4½" OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run 4½" cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut 4½" OD cs 7. Spot 35 sx Cl 8. Spot 35 sx Cl 9. Spot 35 sx Cl 10. Spot 10 sx cm	e foregoing is true	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, p 50', . Set reth 3368' thru etween all ated from t 1 (100' plu 1 (100') in e, erect re e and correct	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10. n & out of egulation of rITLE	n on 8/31/75. & 3352-3368" Circulated t TOC @ 2250'. sx Cl C w/4% @ approx 225% 4 ¹ '' OD csg ss 50' across tow 8-5/8" csg ss dry hole marka	No oth o surface gel. 1 0'& put tub p of sa hoe @ 28 er, clea	her zones ce. Pull out o ll. lt @ 1000' 88'. an & level	of inter f retr & location
This well was prest exist above press TD 3530', PBD 34 8-5/8" OD 20# cs 4½" OD 9.5# csg Propose to P&A at 1. Rig up, insta 2. Run bit & scr 3. Run 4½" cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut 4½" OD cs 7. Spot 35 sx Cl 8. Spot 35 sx Cl 9. Spot 35 sx Cl 10. Spot 10 sx cm	e foregoing is true	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, p 50', . Set reth 3368' thru etween all ated from t 1 (100' plu 1 (100') in e, erect re e and correct	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10. n & out of egulation of rITLE	n on 8/31/75. & 3352-3368" Circulated t TOC @ 2250'. sx Cl C w/4% @ approx 225% 4 ¹ '' OD csg ss 50' across tow 8-5/8" csg ss dry hole marka	No oth o surface gel. 1 0'& put tub p of sa hoe @ 28 er, clea	her zones ce. Pull out o ll. lt @ 1000' 88'. an & level DATE	of inter f retr & location
This well was pre- exist above press TD 3530', PBD 34 8-5/8" OD 20# cs 4½" OD 9.5# csg Propose to P&A a 1. Rig up, insta 2. Run bit & scr 3. Run 4½" cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut 4½" OD cs 7. Spot 35 sx Cl 8. Spot 35 sx Cl 9. Spot 35 sx Cl 10. Spot 10 sx cm	e foregoing is true	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, p 50'. Set retr 3368' thru etween all ated from t 1 (100' plu 1 (100') in e, erect re e) T	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10. n & out of egulation of retrLE	n on 8/31/75. & 3352-3368" Circulated t TOC @ 2250'. sx Cl C w/4% @ approx 2256 4 ¹ " OD csg ss 50' across top 8-5/8" csg ss dry hole marka	No oth o surface gel. 1 0'& put tub p of sa hoe @ 28 er, clea	her zones ce. Pull out o ll. lt @ 1000' 88'. an & level DATE	of inter f retr & location
This well was prest exist above press TD 3530', PBD 34 8-5/8" OD 20# cs 4½" OD 9.5# csg Propose to P&A at 1. Rig up, insta 2. Run bit & scr 3. Run 4½" cmt r 4. Squeeze cmt p spot 2 sx on 5. Fill hole w/h 6. Cut 4½" OD cs 7. Spot 35 sx Cl 8. Spot 35 sx Cl 9. Spot 35 sx Cl 10. Spot 10 sx cm	e foregoing is true	0% water wi this well ent perfs : 8' & cmtd w ' & cmtd w ull rods, p 50'. Set retr 3368' thru etween all ated from t 1 (100' plu 1 (100') in e, erect re e) T	hen shut i 3289-3321' w/200 sx. /300 sx. pump & tbg r @ 3250'. retr w/35 plugs. free point ug) across ug) 950-10. n & out of egulation of rITLE	n on 8/31/75. & 3352-3368" Circulated t TOC @ 2250'. sx Cl C w/4% @ approx 2256 4 ¹ " OD csg ss 50' across top 8-5/8" csg ss dry hole marka	No oth o surface gel. 1 0'& put tub p of sa hoe @ 28 er, clea	her zones ce. Pull out o ll. lt @ 1000' 88'. an & level DATE	of inter f retr & location

RECEIVED

OCT 8 1975

O. C. C.

