

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 12-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

3a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator <b>Harvey E. Yates Company</b>		
Address of Operator <b>P. O. Box 1933, Roswell, New Mexico 88201</b>		
Location of Well		
UNIT LETTER <b>D</b>	<b>990</b> FEET FROM THE <b>North</b> LINE AND <b>660</b> FEET FROM THE <b>West</b> LINE, SECTION <b>34</b> TOWNSHIP <b>7S</b> RANGE <b>30E</b> NMPM.	

7. Unit Agreement Name
8. Farm or Lease Name <b>Heyco Crosby J</b>
9. Well No. <b>1</b>
10. Field and Pool, or Wildcat <b>Wildcat</b>
11. Elevation (Show whether DF, RT, GR, etc.) <b>4100' KB</b>
12. County <b>Chaves</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPERATIONS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
WILL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-13-79 MI cable tools and rig up.  
4-14-79 Clean out to TD of 850'. 750' of 8 5/8" casing hanging in the hole. Ran into junk and iron, cannot continue to drill. Request permission to plug and abandon as follows:

Pull 8 5/8" casing out of hole and use 2 3/8" tubing to spot the following plugs:

Plug #1 - 100' plug from 750' - 850'  
Plug #2 - 100' plug from 240' - 340'  
10 Sx surface plug with dry hole marker set on top.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

WITNESSED BY Anne Pope TITLE Adm. Asst. DATE 6-12-79

APPROVED BY Jerry Sexton TITLE Dist. L. Supv. DATE JUN 14 1979

CONDITIONS OF APPROVAL, IF ANY

RECEIVED

JUN 13 1979

OIL COMMISSION OF TEXAS  
HOUSTON, TEXAS