	1 4.	M. C. C.	C. CUPT	NMOJO	/03*	
Form 2-331 (May 1963)	UNI <sup>^</sup> D ST DEPARTMEN . OF T		SUBMIT IN TRIPLI (Other instructions verse side)	Te Form appro Budget Burg 5. LEASE DESIGNATION	AND SERIAL	
	GEOLOGICAL	. SURVEY		<b>₹₩_019</b>		
÷ • •	IDRY NOTICES AND form for proposals to drill or to Use "APPLICATION FOR PERI			6. IF INDIAN, ALLOTTI	FE OR TRIBE	
1. OIL GAS WELL WELL	🗌 отных Dry H	ole		7. UNIT AGREEMENT N	AMB	
2. NAME OF OPERATOR Jack L. McClellan 3. ADDRESS OF OPERATOR Box 848, Roswell N.M. 88201 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.)					8. FARM OR LEASE NAME BAM Federal 9. WELL NO.	
				1		
				10. FIELD AND POOL,	OR WILDCAT	
At surface	uw.,			Wildcat		
660' FSL & 660' FWL				11. SBC., T., R., M., OR SURVEY OR ARE Sec. 21-	<b>A</b>	
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)				12. COUNTY OR PARIS	·	
			58 G.L.	Chaves	N.M.	
<b>16</b> .	Check Appropriate Roy		lature of Notice, Report, o	r Other Data		
	CHECK Appropriate box			BEQUENT REPORT OF:		
TEST WATER SHUT-	<b>—</b> —1		WATER SHUT-OFF	REPAIRING	WBLL	
FRACTURE TREAT	MULTIPLE COMPLE		FRACTURE TREATMENT	ALTERING		
SHOOT OB ACIDIZE	ABANDON*	X	SHOOTING OR ACIDIZING	ABANDONMI	DNT*	
REPAIR WELL (Other)	CHANGE PLANS		(Other)	ults of multiple completion	on Well	
Kill well	• plug and abandon with heavy mud.( • 100' plug in a	n this te Nitrogen	Gas). Spot 100	' cement plug	at	
Kill well T.D. Plac above the 100' plug	plug and abandon	n this te Nitrogen nd out of ll spot l " casing.	est as follows: Gas). Spot 100 4 1/2" casing. 100' plug at base 16 near surface	If the Stub : e of salt. Spo e will fill	i <b>s</b> ot	
Kill well T.D. Plac above the 100' plug	plug and abandon with heavy mud.( e 100' plug in an baso of salt, will at stub of 8 5/8	n this te Nitrogen nd out of ll spot l " casing.	est as follows: Gas). Spot 100 4 1/2" casing. 00' plug at bas 16 near surface y hole marker as RECEIVE	If the Stub : e of salt. Spo e will fill nd clean loca	i <b>s</b> ot	
Kill well T.D. Plac above the 100' plug	plug and abandon with heavy mud.( e 100' plug in an baso of salt, will at stub of 8 5/8	n this te Nitrogen nd out of ll spot l " casing.	est as follows: 1 Gas). Spot 100 2 4 1/2" casing. 100' plug at basis 16 near surface y hole marker as RECEIVE MAR 2 4 1970	If the Stub : e of salt. Spo e will fill nd clean loca	is ot tion.	
Kill well T.D. Plac above the 100' plug	plug and abandon with heavy mud.( e 100' plug in an baso of salt, will at stub of 8 5/8	n this te Nitrogen nd out of ll spot l " casing.	est as follows: Gas). Spot 100 4 1/2" casing. 00' plug at bas 16 near surface y hole marker as RECEIVE	If the Stub : e of salt. Spo e will fill nd clean loca	is ot tion.	
Kill well T.D. Place above the 100' plug balance of balance of 18. I hereby certify that SIGNED	plug and abandon with heavy mud.( e 100' plug in an baso of salt, with at stub of 8 5/8' pipe with cement the method is true and correct 20 Milford	n this te Nitrogen nd out of 11 spot 1 " casing. t, set dr	est as follows: 1 Gas). Spot 100 2 4 1/2" casing. 100' plug at bas 15 near surface y hole marker as RECEIVE MAR 2 4 1970	If the stub : e of salt. Spo e will fill nd clean loca	is ot tion.	
Kill well T.D. Place above the 100' plug balance of 18. I hereby certify that SIGNED (This space for Fede APPROVED BY	plug and abandon with heavy mud.( e 100' plug in an baso of salt, with at stub of 8 5/8' pipe with cement the action is true and correct 20 Millord ral or State office (**)	n this te Nitrogen nd out of 11 spot 1 " casing. t, set dr	est as follows: A Gas). Spot 100 4 1/2" casing. 100' plug at basis If near surface by hole marker as R E C E I V E MAR 2 4 1970 ARTESIA, OFFICE	If the stub : e of salt. Spo e will fill nd clean loca ED RECENT	is ot tion.	
Kill well T.D. Place above the 100' plug balance of 18. I hereby certify that SIGNED (This space for Fede APPROVED BY	plug and abandon with heavy mud.( e 100' plug in an baso of salt, with at stub of 8 5/8' pipe with cement the method is true and correct 20 Milford	n this te Nitrogen nd out of 11 spot 1 " casing. t, set dr	est as follows: A Gas). Spot 100 4 1/2" casing. 100' plug at basis If near surface by hole marker as R E C E I V E MAR 2 4 1970 ARTESIA, OFFICE	If the stub : e of salt. Spe e will fill nd clean loca ED PATE3	is ot tion.	
Kill well T.D. Place above the 100' plug balance of 18. I hereby certify that SIGNED (This space for Fede APPROVED BY	plug and abandon with heavy mud.( e 100' plug in an baso of salt, with at stub of 8 5/8' pipe with cement the control is true and correct 2) M. (Jond ral or State office (***)	n this te Nitrogen nd out of 11 spot 1 " casing. t, set dr	est as follows: A Gas). Spot 100 4 1/2" casing. 100' plug at basis If near surface by hole marker as R E C E I V E MAR 2 4 1970 ARTESIA, OFFICE	If the stub : e of salt. Spe e will fill nd clean loca ED PATE3	is ot tion.	

Q.

-

•

MAR 2 5 1970 MAR 2 5 1970 MMON COMSERVATION COMM

CIT A FIRME

OIL CONSERVATION COMM.