

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

NMOCC COPY

SUBMIT IN TRIPlicate
(Other Instructions
on Reverse Side)

Form approved
Budget Office No. 42-RL224
5. LEASE DESIGNATION AND SERIAL NO.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☒ GAS WELL ☐ OTHER 2. NAME OF OPERATOR UNION TEXAS PETROLEUM CORPORATION 3. ADDRESS OF OPERATOR 1300 Wilco Building, Midland, Texas 79701 4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit Letter "P", 660' FSL & 660' FEL 14. PERMIT NO. 15. ELEVATIONS (Show whether DP, RT, CR, etc.) 4288.7' GR	6. IF INDIAN, ALLOTTEE OR TRIBE NAME 7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME Federal "33" 9. WELL NO. 1 10. FIELD AND POOL, OR WELDCAT Tom-Tom (San Andres) 11. SEC., T., R., M., OR BLM. AND SURVEY OR AREA Sec. 33, T-7-S, R-31-E 12. COUNTY OR PARISH Chaves 13. STATE New Mexico
--	---

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF ☐	PULL OR ALTER CASING ☐	WATER SHUT-OFF ☐	REPAIRING WELL ☐
FRACURE TREAT ☐	MULTIPLE COMPLETE ☐	FRACURE TREATMENT ☐	ALTERING CASING ☐
SHOOT OR ACIDIZE ☐	ABANDON* ☐	SHOOTING OR ACIDIZING ☐	ABANDONMENT* ☐
REPAIR WELL ☐	CHANGE PLANS ☐	(Other) ☐	(Other) ☐
(Other) Plug & Abandon ☒		(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

1. Re-enter well and displace hole w/10#/gal. mud laden fluid.
2. Cut off 4½" casing @ approximated 3000' (Top of cement @ 3090') and pull this casing.
3. Set 35 sx. plug (100' in & out) of 4½" stud.
4. Set 35 sx. plug (50' above & below) the top of salt section @ 1530'.
5. Set 35 sx. plug at bottom of 8 5/8" casing @ 401'.
6. Well will be permanently plugged and abandoned by setting a 10 sx. plug in top of 8 5/8" with a dry hole marker.

RECEIVED

MAY 31 1977

**U.S. GEOLOGICAL SURVEY
ARTESIA, NEW MEXICO**

18. I hereby certify that the foregoing is true and correct

SIGNED <i>Terley H. J. H.</i>	TITLE Sr. Prod. Analyst	DATE May 26, 1977
(This space for Federal or State office use)		
APPROVED BY <i>Joe S. Lara</i>	TITLE ACTING DISTRICT ENGINEER	DATE JUN 3 - 1977
CONDITIONS OF APPROVAL, IF ANY:		

subject to placing a 25-sx plug across the perforations *See Instructions on Reverse Side

RECEIVED
JUN 13 1977
U.S. CONSERVATION COMM.
WASH. D. C.

RECEIVED
JUN 6 1977
O.C.C.
ARTESIA, OFFICE