- DEPA	UNIT STAT		SUBMIT IN TRIPL (Other instructions verse side)	0 +	Form app Budget Bu EASE DESIGNATI	ireau No. 4
	GEOLOGICAL SL	URVEY	- · ·		NM-1663	33
	NOTICES AND RE proposals to drill or to deep PPLICATION FOR PERMIT-				F INDIAN, ALLOT	TEE OR TRI
1. OIL GAS WELL OTHER				7. 0	7. UNIT AGREEMENT NAME	
2. NAME OF OPERATOR				8. F	8. FARM OR LEASE NAME	
Yates Drilling Company					Estelle Federal	
3. ADDRESS OF OPERATOR		00010		9. W	ELL NO.	
207 So. 4th St., Artesia, NM 88210 4. Togration of well, (Report location clearly and in accordance with any State requirements.*				10.	FIELD AND POOL	., OR WILDC
See also space 17 below.) At surface					Und. Que	een
660' FWL & 1980'	FNL of Sec. 3	34-T12S-R	30E	11.	SEC., T., R., M., C SUEVEY OR A nit E	OR BLK. AND
				Se	c. 34-12	
14. PERMIT NO.	15. ELEVATIONS (Sho		GK, EIC.)		COUNTY OR PAR	
	3925				<u>Chaves</u>	<u> </u>
16. Che	ck Appropriate Box To	Indicate Natu	re of Notice, Repo	ort, or Other	Data	100 C
NOTICE OF	F INTENTION TO:			SUBSEQUENT F	REPORT OF:	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	G	WATER SHUT-OFF		REPAIRIN	G WELL
FRACTURE TREAT	MULTIPLE COMPLETE		FRACTURE TREATME			G CASING
SHOOT OR ACIDIZE	ABANDON* CHANGE PLANS		SHOOTING OR ACIDIZ		ABANDON	MENT*
(Other)			(NOTE: Repor	t results of ma Recompletion	iltiple completi Report and Log	on on Well
nent to this work.)* Perf. well fr 15% HCL acid.	om 2205 to 222 Swab tested. from 2137-42	23 - 20 h No oil o:	oles - acid r gas show.	ized wi Set E	th 1000 -Z dril:	gallo l plug
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	om 2205 to 222 Swab tested.	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19	ized wi Set E ed with . Well et 50 s 70 - ci	th 1000 -Z dril 500 ga plugged x plug a rcl mud	gallo l plug llons l with above
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at	or 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19	ized wi Set E ed with . Well et 50 s 70 - ci	th 1000 -Z dril 500 ga plugged x plug a rcl mud	gallo l plug llons l with above . Set
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	or 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with . Well et 50 s 70 - ci e Marke	th 1000 -Z drill 500 gal plugged x plug a rcl mud r. Comp	gallo l plug llons l with above . Set pleted
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	or 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with . Well et 50 s 70 - ci e Marke	th 1000 -Z drill 500 gal plugged x plug a rcl mud r. Comp	gallo l plug llons l with above . Set pleted
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	or 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with . Well et 50 s 70 - ci e Marke	th 1000 -Z drill 500 gal plugged x plug a rcl mud r. Comp	gallo l plug llons l with above . Set pleted
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	or 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with . Well et 50 s 70 - ci e Marke	th 1000 -Z drill 500 gal plugged x plug a rcl mud r. Comp	gallo l plug llons l with above . Set pleted
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	or 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with . Well et 50 s 70 - ci e Marke	th 1000 -Z dril: 500 gal plugged x plug a rcl mud. r. Comp	gallo l plug llons l with above Set oleted
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	or 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with Well et 50 s 70 - ci e Marke	th 1000 -Z drill 500 gal plugged x plug a rcl mud r. Comp	gallo l plug llons d with above Set oleted
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	or 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with Well et 50 s 70 - ci e Marke	th 1000 -Z drill 500 gal plugged x plug a rcl mud r. Comp	gallo l plug llons d with above Set oleted
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	or 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with Well et 50 s 70 - ci e Marke	th 1000 -Z drill 500 gal plugged x plug a rcl mud r. Comp	gallo l plug llons d with above Set oleted
<pre>proposed work. If well is nent to this work.)* Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at work 1/5/79.</pre>	directionally drilled, give su com 2205 to 222 Swab tested. from 2137-42 Swab tested. Ictions by Ray 2094. Waited surface via t	23 - 20 h No oil oi - 10 hol No oil o Stalls, - tagged	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with Well et 50 s 70 - ci e Marke	th 1000 -Z dril: 500 gal plugged x plug a rcl mud. r. Comp	gallo l plug llons d with above Set oleted
Perf. well fr Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at	directionally drilled, give su com 2205 to 222 Swab tested. from 2137-42 Swab tested. actions by Ray 2094. Waited surface via t	23 - 20 h No oil o - 10 hol No oil o Stalls, - tagged cubing.	and measured and tri oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with Well et 50 s 70 - ci e Marke	th 1000 -Z dril: 500 gal plugged x plug a rcl mud r. Comp 9 - 1979 9 - 1979 DLUGIONE SU NEW MEN	gallo l plug llons d with above Set oleted
Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at work 1/5/79. 18. I hereby certify that the fore SIGNED Methodson	directionally drilled, give su com 2205 to 222 Swab tested. from 2137-42 Swab tested. Ictions by Ray 2094. Waited surface via t	23 - 20 h No oil o - 10 hol No oil o Stalls, - tagged cubing.	oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with Well et 50 s 70 - ci e Marke	th 1000 -Z dril: 500 ga plugged x plug a rcl mud r. Comp 9 - 1979 9 - 1979 JLUGIONE SU JLUGIONE SU JLUGIONE SU JATE 1	gallo l plug llons d with above Set oleted
Perf. well fr 15% HCL acid. at 2190 perf. 15% HCL acid. verbal instru top perfs at 15 sx plug at work 1/5/79. 18. I hereby certify that the fore SIGNED Methodson	directionally drilled, give su om 2205 to 222 Swab tested. from 2137-42 Swab tested. Ictions by Ray 2094. Waited surface via t surface via t	23 - 20 h No oil o - 10 hol No oil o Stalls, - tagged cubing.	oles - acid r gas show. es. Acidiz or gas show U.S.G.S. S plug at 19 Set Dry Hol	ized wi Set E ed with Well et 50 s 70 - ci e Marke	th 1000 -Z dril: 500 ga plugged x plug a rcl mud r. Comp 9 - 1979 9 - 1979 JLUGIONE SU JLUGIONE SU JLUGIONE SU JATE 1	gallo l plug llons l with above Set oleted

RECEIVED

-

JAN 2

O. C. I

RECEIVED JAN 31 1980 OIL CONSERVATION DIV.