

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
ALBUQUERQUE, NEW MEXICO 88240

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.  
NM 15446

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Rebecca Crosby

9. WELL NO.  
2

10. FIELD AND POOL, OR WILDCAT  
Cato-San Andres

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

Sec. 31, T7S, R31E

12. COUNTY OR PARISH  
Chaves

13. STATE  
NM

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

MAR 9 1987

2. NAME OF OPERATOR

Yates Energy Corporation

BU  
RC

3. ADDRESS OF OPERATOR

Sunwest Centre Suite 1010, Roswell, NM 88201

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

660' FEL & 660' FSL

14. PERMIT NO.

15. ELEVATIONS (Show whether DP, RT, CR, etc.)

4340.4 GL

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON\*

SHOOTING OR ACIDIZING

ABANDONMENT\*

REPAIR WELL

CHANGE PLANS

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

1. Set CIBP @ 3650' with 35' cmt plug on top of it.
2. Attempt to cut and pull 4 1/2" csg. @ 2550'.
3. Set 100' cmt plug @ 2600' (50' in and 50' out of 4 1/2" csg.) tag this plug.
4. Set 100' cmt plug @ 1323' (50' out of 8 5/8" csg. and 50' inside) tag this plug.
5. Set 50' cmt plug @ surface and install dry hole marker.
6. Clean location

Verbal approval as per Mr. Peter Chester 3/5/87

18. I hereby certify that the foregoing is true and correct

SIGNED

Sharon Hill

TITLE

Production Analyst

DATE

March 5, 1987

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED  
DATE  
PETER W. CHESTER

MAR 16 1987

\*See Instructions on Reverse Side