

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
N. M. SUBSURFACE BUREAU  
OTHER INSTRUCTIONS  
O. BOX 1980  
HOBBS, NEW MEXICO 88240

Form approved.  
Budget Bureau No. 1004-0135  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Western Reserves Oil Co., Inc.	8. FARM OR LEASE NAME Western Reserves 34 Federal
3. ADDRESS OF OPERATOR P. O. Box 993, Midland, Tx 79702	9. WELL NO. "34" Federal #2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface 330'N 830'E API 30-005-20721	10. FIELD AND POOL, OR WILDCAT Tom-Tom (San Andres)
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA S-34, T-7S, R-31E
15. ELEVATIONS (Show whether DF, RT, CR, etc.)	12. COUNTY OR PARISH Chavez
	13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input checked="" type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.) \*

1. Run in hole with tubing to 3900' and spotted 35 sks. of cement. WOC.
2. Cut and pull 4 1/2" casing from 1751'.
3. Spot 40 sks. of cement @ 1800'. WOC. No tag. Respot 40 sks. & WOC. Tagged plug @ 1593'.
4. Spot 10 sks. of cement @ surface plug. Install P & A marker. 6-16-89

As per  
phone call to  
Kelly Green on  
8-13-98 JH

Sold 1-1-1991

18. I hereby certify that the foregoing is true and correct

SIGNED Raymond Maldonado/KH TITLE P & A Supervisor  
Baber Well Serv., Cementer DATE 7-28-89

(This space for Federal or State office use)

APPROVED BY \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY:

TITLE \_\_\_\_\_  
Approved as to plugging of the well bore.  
Liability under bond is retained until  
surface restoration is completed.

\*See Instructions on Reverse Side

DATE APPROVED  
PETER W. CHESTER  
AUG 11 1989  
BUREAU OF LAND MANAGEMENT  
ROSWELL, NEW MEXICO  
RESOURCE AREA