

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
L-5124	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry hole		7. Unit Agreement Name
2. Name of Operator McClellan Oil Corporation		8. Farm or Lease Name Loco
3. Address of Operator Post Office Drawer 730, Roswell, New Mexico 88201		9. Well No. 1
4. Location of Well UNIT LETTER F, 1980 FEET FROM THE N LINE AND 1980 FEET FROM THE W LINE, SECTION 19 TOWNSHIP 14-S RANGE 30-E NMPM.		10. Field and Pool, or Wildcat S.E. Chaves Queen Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3837' G.L.		12. County Chaves

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pursuant to verbal instructions, this test will be plugged and abandoned as follows:

100' plug over the San Andres 2590-2680'.
100' plug over the Queen sand 1950-2050'.
100' plug over the top of salt 525-625'.
100' plug in and out of 8-5/8" casing 400-500'.
10 sx plug at surface.
Heavy mud to be pumped between all plugs.
Set surface marker and restore surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Jerry Sexton TITLE Operator DATE 5/18/81

APPROVED BY Jerry Sexton TITLE DATE

CONDITIONS OF APPROVAL, IF ANY: