form 9331 Dec. 1973	NM OIL CONS. COMMISSI Drawer DD Artesia, NM 88210 UNITED STATES	ON Form Approved. Budget Bureau No. 42-R14
	UNITED STATES 58210 DEPARTMENT OF THE INTERIOR GEOLOGICAL SURVEY	5. LEASE <u>NM - 067707</u> 6. IF INDIAN, ALLOTTEE OR TRIBE NAME
	NOTICES AND REPORTS ON WELLS m for proposals to drill or to deepen or plug back to a different 9-331-C for such proposals.)	7. UNIT AGREEMENT NAME 8. FARM OR LEASE NAME AUG 0
1. oil well	gas well other	Siete-Federal 9. WELL NO. O. (
2. NAME OF O		2 10. FIELD OR WILDCAT NAME
Petroleum 3. ADDRESS O	Exploration Company, Inc.	Siete-San Andres
P O Box	809 Roswell, New Mexico 88201	11. SEC., T., R., M., OR BLK AND SURVEY AREA
4. LOCATION C below.) AT SURFACE AT TOP PRO	DF WELL (REPORT LOCATION CLEARLY, See space 17 E: 1980' FNL & 660' FEL DD. INTERVAL: Same	Sec. 17, T-8-S, R-31-E, N. 12. COUNTY OR PARISH 13. STATE Chaves New Mexico
AT TOTAL D	ROPRIATE BOX TO INDICATE NATURE OF NOTICE,	14. API NO.
	R OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND 4210 4 GR 4218 KB
REQUEST FOR	APPROVAL TO: SUBSEQUENT REPORT OF:	4210.4 GR 4218 KB
TEST WATER SH FRACTURE TREA SHOOT OR ACII REPAIR WELL		(NOTE: Report results of multiple completion or change on Form 9-330.)
MULTIPLE COM CHANGE ZONES ABANDON* (other) Surfa	ace_CasingXX	DISTRICT
MULTIPLE COM CHANGE ZONES ABANDON* (other) Surfa 17. DESCRIBE including es measured a	PLETE ACE Casing XX PROPOSED OR COMPLETED OPERATIONS (Clearly sta stimated date of starting any proposed work. If well is and true vertical depths for all markers and zones pertine	te all pertinent details, and give pertinent d directionally drilled, give subsurface locations ent to this work.)*
MULTIPLE COM CHANGE ZONES ABANDON* (other) Surfa 17. DESCRIBE	PLETE ACE CasingXX PROPOSED OR COMPLETED OPERATIONS (Clearly sta stimated date of starting any proposed work. If well is and true vertical depths for all markers and zones pertine Spudded 12 1/4" hole at 12:30 P.M.	te all pertinent details, and give pertinent d directionally drilled, give subsurface locations ent to this work.)*
MULTIPLE COM CHANGE ZONES ABANDON* (other) Surfa 17. DESCRIBE including es measured a	PLETE ACE Casing XX PROPOSED OR COMPLETED OPERATIONS (Clearly sta stimated date of starting any proposed work. If well is and true vertical depths for all markers and zones pertine	te all pertinent details, and give pertinent d directionally drilled, give subsurface locations ent to this work.)*
MULTIPLE COM CHANGE ZONES ABANDON* (other) Surfa 17. DESCRIBE including es measured a 7-05-83	PLETE ACE CasingXX_ PROPOSED OR COMPLETED OPERATIONS (Clearly states stimated date of starting any proposed work. If well is and true vertical depths for all markers and zones pertine Spudded 12 1/4" hole at 12:30 P.M. Drilled to 365'. Ran 391.22' of & set at 367' KBM. Cemented with 85 29° C.C. and 100 sx class "C" w/2% Plug down at 1:30 A.M. After W.O.C. for 18 hours, pressur held O.K. Started drilling out shoe at 9:30	te all pertinent details, and give pertinent d directionally drilled, give subsurface locations ent to this work.)* 5/8", 20# casing and 5 sx. Halliburton lite 6 C.C., cement circulated. red up to 1000# for 20" -
MULTIPLE COM CHANGE ZONES ABANDON* (other) Surfa 17. DESCRIBE including es measured a 7-05-83 7-06-83	PLETE ACE CasingXX_ PROPOSED OR COMPLETED OPERATIONS (Clearly sta stimated date of starting any proposed work. If well is and true vertical depths for all markers and zones pertine Spudded 12 1/4" hole at 12:30 P.M. Drilled to 365'. Ran 391.22' of & set at 367' KBM. Cemented with 85 29° C.C. and 100 sx class "C" w/2% Plug down at 1:30 A.M. After W.O.C. for 18 hours, pressur held O.K. Started drilling out shoe at 9:30	te all pertinent details, and give pertinent d directionally drilled, give subsurface locations ent to this work.)* 5/8", 20# casing and 5 sx. Halliburton lite 6 C.C., cement circulated. red up to 1000# for 20" - P.M.
MULTIPLE COM CHANGE ZONES ABANDON* (other) <u>Surfa</u> 17. DESCRIBE including es measured a 7-05-83 7-06-83 Subsurface Saf	PLETE ACE CasingXX PROPOSED OR COMPLETED OPERATIONS (Clearly sta stimated date of starting any proposed work. If well is sind true vertical depths for all markers and zones pertine Spudded 12 1/4" hole at 12:30 P.M. Drilled to 365'. Ran 391.22' of & set at 367' KBM. Cemented with 85 29° C.C. and 100 sx class "C" w/2% Plug down at 1:30 A.M. After W.O.C. for 18 hours, pressur held O.K. Started drilling out shoe at 9:30 Mety Valve: Manu. and Type	te all pertinent details, and give pertinent d directionally drilled, give subsurface locations ent to this work.)* 5/8", 20# casing and 5 sx. Halliburton lite 6 C.C., cement circulated. red up to 1000# for 20" - P.M.
MULTIPLE COM CHANGE ZONES ABANDON* (other) Surfa 17. DESCRIBE including es measured a 7-05-83 7-06-83 Subsurface Saf 18. I hereby of	PLETE ACE CasingXX PROPOSED OR COMPLETED OPERATIONS (Clearly sta stimated date of starting any proposed work. If well is and true vertical depths for all markers and zones pertine Spudded 12 1/4" hole at 12:30 P.M. Drilled to 365'. Ran 391.22' of 8 set at 367' KBM. Cemented with 85 29° C.C. and 100 sx class "C" w/2% Plug down at 1:30 A.M. After W.O.C. for 18 hours, pressur held O.K. Started drilling out shoe at 9:30 Mety Valve: Manu. and Type	te all pertinent details, and give pertinent d directionally drilled, give subsurface locations ent to this work.)* 5/8", 20# casing and 5 sx. Halliburton lite 6 C.C., cement circulated. red up to 1000# for 20" - P.M.
MULTIPLE COM CHANGE ZONES ABANDON* (other) <u>Surfa</u> 17. DESCRIBE including es measured a 7-05-83 7-06-83 Subsurface Saf	PLETE ACE CasingXX PROPOSED OR COMPLETED OPERATIONS (Clearly sta stimated date of starting any proposed work. If well is and true vertical depths for all markers and zones pertine Spudded 12 1/4" hole at 12:30 P.M. Drilled to 365'. Ran 391.22' of 8 set at 367' KBM. Cemented with 85 29° C.C. and 100 sx class "C" w/2% Plug down at 1:30 A.M. After W.O.C. for 18 hours, pressur held O.K. Started drilling out shoe at 9:30 Mety Valve: Manu. and Type	te all pertinent details, and give pertinent d directionally drilled, give subsurface locations ent to this work.)* 5 5/8", 20# casing and 5 sx. Halliburton lite 6 C.C., cement circulated. red up to 1000# for 20" - P.M.
MULTIPLE COM CHANGE ZONES ABANDON* (other) Surfa 17. DESCRIBE including es measured a 7-05-83 7-06-83 Subsurface Saf 18. I hereby es SIGNED	PLETE ACE CasingXX PROPOSED OR COMPLETED OPERATIONS (Clearly sta stimated date of starting any proposed work. If well is and true vertical depths for all markers and zones pertine Spudded 12 1/4" hole at 12:30 P.M. Drilled to 365'. Ran 391.22' of 8 set at 367' KBM. Cemented with 85 29° C.C. and 100 sx class "C" w/2% Plug down at 1:30 A.M. After W.O.C. for 18 hours, pressur held O.K. Started drilling out shoe at 9:30 Started drilling out shoe at 9:30 Market Manu. and Type entify that the foregoing is true and correct	<pre>te all pertinent details, and give pertinent d directionally drilled, give subsurface locations ent to this work.)* 5 5/8", 20# casing and 5 sx. Halliburton lite 5 C.C., cement circulated. red up to 1000# for 20" - P.M. </pre>

ROSWELL, NEW MEXICO

a 🖓 - Se Kalanda Baharan ya

RECEIVED AUG 1 2 1983 HOBELS OFFICE

۰.