

Form 3160-5
(November 1983)
(Formerly 9-331)

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT--" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐
2. NAME OF OPERATOR
McClellan Oil Corporation
3. ADDRESS OF OPERATOR
P.O. Drawer 730 Roswell, NM 88202 505-622-3200
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface
1980' FNL & 660' FEL

5. LEASE DESIGNATION AND SERIAL NO.
NM-19611
6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

McClellan A Federal

9. WELL NO.

#2

10. FIELD AND POOL, OR WILDCAT

Cedar Point *Pelms Kenn*

11. SEC., T., R., M., OR BLK. AND
SURVEY OR ARMA

Sec. 27-T15S-R30E

14. PERMIT NO.
30-005-70906
15. ELEVATIONS (Show whether DF, RT, GR, etc.)
4078' GL

12. COUNTY OR PARISH
Chaves
13. STATE
NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☒
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

Wolfcamp zone

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Plans for recompleting this well, in the Wolf Camp Zone, are as follows:

1. Set CIBP at 9000'. Dump ^{35'} 50' of cmt on top.
2. Load hole w/2% KCL.
3. Perf interval 8100'-8170'/
4. Run RTTS to 8050'. Break down & acidize zone.
5. Test zone.
6. Commencement date approx. 1/27/91

18. I hereby certify that the foregoing is true and correct

SIGNED

Mark L. Lee

TITLE

Dir. & Comp. Engr

DATE

1-4-91

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED
DATE

JAN 11 1991

*See Instructions on Reverse Side

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA