RECEIVED BY - NM OIL CONS. CO Drawer DD	<u>/ 11</u> 24 - 000 - 0-1		
	5z10	Form Approved. Budget Bureau No.	42-R14
JUN 2 1 1984 UNITED STATES	5. LEASE		
O. C. D. DEPARTMENT OF THE INTERIOR	NM	19197	
ARTESIA, OFFICE GEDLOGICAL SURVEY	6. IF INDIAN, AL	LLOTTEE OR TRIBE N	AME
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREE	MENT NAME	
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)			
1. oil	8. FARM OR LE		
1. oli gas well well other	9. WELL NO.	redetat	
2. NAME OF OPERATOR	#1 .		
Petroleum Exploration Company, Inc.	10. FIELD OR WI	LDCAT NAME	
3. ADDRESS OF OPERATOR	The second se	San Andres	
Post Office Box 809, Roswell, NM 88201 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., AREA	M., OR BLK. AND SU	RVEY
below.)		<u>F-8-S, R-31-</u>	
AT SURFACE: 660' FWL and 660' FNL AT TOP PROD. INTERVAL: Same		PARISH 13. STATE	
AT TOTAL DEPTH: Same	Chaves		<u> </u>
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,			-
REPORT, OR OTHER DATA	15. ELEVATIONS 4283 GI	SHOW DF, KDB,	AND W
REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:			
TEST WATER SHUT-OFF	4		
FRACTURE TREAT			
SHORIT OF ACTOURS 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			
REPAIR WELL	,	with of multiple complete	ion
REPAIR WELL	(NOTE: Report res	wite of multiple complet N Form 9–330.)	ion ar z
	(NOTE: Report res		ion or z
REPAIR WELL  PULL OR ALTER CASING  MULTIPLE COMPLETE	(NOTE: Report res		ion ar z
REPAIR WELL     Image: Constraint of the second secon	(NOTE: Report res		ion or z
REPAIR WELL	(NOTE: Report rea change on	i Form 9–330.)	ent dat
REPAIR WELL       Image: Construction of the second starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent.	(NOTE: Report rea change on e all pertinent deta lirectionally drilled, nt to this work.)*	Form 9-330.) hils, and give pertine give subsurface loca	ent dat tions a
REPAIR WELL       Image: Construction of the second s	(NOTE: Report rea change on e all pertinent deta lirectionally drilled, it to this work.)* requests pe	ils, and give pertine give subsurface loca	ent dat tions a
REPAIR WELL       Image: Construction of the second starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinent.	(NOTE: Report rea change on e all pertinent deta lirectionally drilled, it to this work.)* requests pe	ils, and give pertine give subsurface loca	ent dat tions a
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON• (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner Petroleum Exploration Company, Inc. plug and abandon the above reference	(NOTE: Report rea change on e all pertinent deta lirectionally drilled, it to this work.)* requests pe d well as f	Form 9-330.) hils, and give pertine give subsurface loca ermission to follows:	ent dat tions a
REPAIR WELL       Image: Construction of the second s	(NOTE: Report rea change on e all pertinent deta lirectionally drilled, it to this work.)* requests pe d well as f	Form 9-330.) hils, and give pertine give subsurface loca ermission to follows:	ent dat tions a
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON• (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner Petroleum Exploration Company, Inc. plug and abandon the above reference 1) Set cast iron bridge plug plug.	(NOTE: Report rea change on e all pertinent deta lirectionally drilled, it to this work.)* requests pe d well as f at 3800', I	Form 9-330.) hils, and give pertine give subsurface loca ermission to follows:	ent dat tions a
REPAIR WELL       Image: Complete c	(NOTE: Report rea change on e all pertinent deta lirectionally drilled, it to this work.)* requests pe id well as f at 3800', I 00'.	ils, and give pertine give subsurface loca ermission to follows: Dump 35' cem	ent dat tions a nent
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON• (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner Petroleum Exploration Company, Inc. plug and abandon the above reference 1) Set cast iron bridge plug plug.	(NOTE: Report rea change on e all pertinent deta lirectionally drilled, it to this work.)* requests pe id well as f at 3800', I 00'.	ils, and give pertine give subsurface loca ermission to follows: Dump 35' cem	ent dat tions a nent
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON• (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinen Petroleum Exploration Company, Inc. plug and abandon the above reference 1) Set cast iron bridge plug plug. 2) Perforate 4½" casing at 13 3) Set cast iron cement retai	(NOTE: Report reachange on change on e all pertinent deta lirectionally drilled, nt to this work.)* requests pe d well as f at 3800', I 00'. ner at 1200	ils, and give pertine give subsurface loca ermission to follows: Dump 35' cem	ent dat tions a nent
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON• (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertinen Petroleum Exploration Company, Inc. plug and abandon the above reference 1) Set cast iron bridge plug plug. 2) Perforate 4½" casing at 13 3) Set cast iron cement retai with 90 sacks cement.	(NOTE: Report reachange on change on e all pertinent deta lirectionally drilled, nt to this work.)* requests pe d well as f at 3800', I 00'. ner at 1200	ils, and give pertine give subsurface loca ermission to follows: Dump 35' cem	ent dat tions a nent
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON• (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner Petroleum Exploration Company, Inc. plug and abandon the above reference 1) Set cast iron bridge plug plug. 2) Perforate 4½" casing at 13 3) Set cast iron cement retai with 90 sacks cement. 4) Set 10 sacks cement plug a	(NOTE: Report reachange on change on e all pertinent deta lirectionally drilled, nt to this work.)* requests pe d well as f at 3800', I 00'. ner at 1200	ils, and give pertine give subsurface loca ermission to follows: Dump 35' cem	ent dat tions a nent
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON• (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner Petroleum Exploration Company, Inc. plug and abandon the above reference 1) Set cast iron bridge plug plug. 2) Perforate 4½" casing at 13 3) Set cast iron cement retai with 90 sacks cement. 4) Set 10 sacks cement plug a	(NOTE: Report reachange on change on e all pertinent deta lirectionally drilled, nt to this work.)* requests per id well as f at 3800', I 00'. ner at 1200	ils, and give pertine give subsurface loca ermission to follows: Dump 35' cem	ent dat tions a nent
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON• (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner Petroleum Exploration Company, Inc. plug and abandon the above reference 1) Set cast iron bridge plug plug. 2) Perforate 4½" casing at 13 3) Set cast iron cement retai with 90 sacks cement. 4) Set 10 sacks cement plug a	(NOTE: Report reachange on change on e all pertinent deta lirectionally drilled, it to this work.)* requests pe d well as f at 3800', I 00'. ner at 1200 t surface.	Form 9-330.) hils, and give pertine give subsurface loca ermission to follows: Dump 35' cem D', cement s	ent dat tions a nent
REPAIR WELL       Image: Complete c	(NOTE: Report reachange on change on e all pertinent deta lirectionally drilled, it to this work.)* requests pe d well as f at 3800', I 00'. ner at 1200 t surface.	Form 9-330.) hils, and give pertine give subsurface loca ermission to follows: Dump 35' cem D', cement s	ent dat tions a nent
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner Petroleum Exploration Company, Inc. plug and abandon the above reference 1) Set cast iron bridge plug plug. 2) Perforate 4½" casing at 13 3) Set cast iron cement retai with 90 sacks cement. 4) Set 10 sacks cement plug a 5) Install dry hole marker. Subsurface Sefety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct	(NOTE: Report reachange on change on e all pertinent deta lirectionally drilled, it to this work.)* requests per ad well as f at 3800', I 00'. ner at 1200 t surface.	Form 9-330.) hils, and give pertine give subsurface loca ermission to Eollows: Dump 35' cem D', cement s	ent dat tions a lent
REPAIR WELL       Image: Construction of the state of th	(NOTE: Report reachange on change on irrectionally drilled, it to this work.)* requests per ed well as f at 3800', I 00'. ner at 1200 t surface.	Form 9-330.) hils, and give pertine give subsurface loca ermission to Eollows: Dump 35' cem D', cement s	ent dat tions a lent
REPAIR WELL PULL OR ALTER CASING MULTIPLE COMPLETE CHANGE ZONES ABANDON* (other) 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner Petroleum Exploration Company, Inc. plug and abandon the above reference 1) Set cast iron bridge plug plug. 2) Perforate 4½" casing at 13 3) Set cast iron cement retai with 90 sacks cement. 4) Set 10 sacks cement plug a 5) Install dry hole marker. Subsurface Sefety Valve: Manu. and Type 18. I hereby certify that the foregoing is true and correct	(NOTE: Report reachange on change on e all pertinent deta lirectionally drilled, it to this work.)* requests per ad well as f at 3800', I 00'. ner at 1200 t surface.	Form 9-330.) wils, and give pertine give subsurface loca ermission to Eollows: Dump 35' cem D', cement s Set @ /25/84	ent dat tions a lent

. \*

.

tructions on Neverse

Side

>

