| Submit 3 Copies to Appropriate | Energy, Minerals and Natural Resources Department | | Form C-103 Revised 1-1-89 | |
|--|---|--|---|--|
| DISTRICT I | OIL CONSERVATION | N DIVISION | | |
| O. Box 1980, Hobbs, NM 88240 P.O. Box 2088 | | WELL API NO. 30-005-20914 | | |
| Santa Fe, New Mexico 87504-2088 P.O. Drawer DD, Artesia, NM 88210 | | 5. Indicate Type of Lease STATE XX FEE | | |
| DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410 | | | 6. State Oil & Gas Lease No. LG 1289 | |
| SUNDRY NOTICES AND REPORTS ON WELLS | | | | |
| (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | | | 7. Lease Name: or Unit Agreement Name | |
| I. Type of Well: OIL GAS WELL WELL OTHER P&A | | Union XJ State | | |
| 2. Name of Operator | - | | 8. Well No. | |
| YATES PETROLEUM CORPO | RATION | | 9. Pool name or Wildcat | |
| 3. Address of Operator 105 South 4th St., Ar | tesia, NM 88210 | | Tom Tom San Andres | |
| 4. Well Location Unit Letter B : 330 Feet From The North Line and 1650 Feet From The East Line | | | | |
| 2 | Township 8S Ran | 31E | NMPM Chaves County | |
| Section 2 10 Winship Range RAM 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4349.1' GR | | | | |
| Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: | | | | |
| PERFORM REMEDIAL WORK | PLUG AND ABANDON | REMEDIAL WORK | ALTERING CASING | |
| TEMPORARILY ABANDON | CHANGE PLANS | COMMENCE DRILLIN | G OPNS. PLUG AND ABANDONMENT X | |
| PULL OR ALTER CASING | | CASING TEST AND C | EMENT JOB L | |
| OTHER: | | OTHER: | | |
| 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. | | | | |
| Plugged and abandoned well as follows: Set CIBP @ 3875' w/cement on top. Circulate hole with mud. Cut casing at 2300' and pull. Spot 30 sx cement plug at 2350'. Tag plug @ 2246'. Spot 80 sx cement plug at 2080' Spot 90 sx cement plug at 1720'. Tag plug at 1580'. Spot 30 sx cement plug at 400'. POOH to 37'. Circulate cement to surface. | | | | |
| Install regulation abandonment marker. Plugging completed 1-15-92. | | | | |
| | | | | |
| | | | | |
| | | | | |

TELEPHONE NO. 505/748-1471Juanita Goodlett TYPE OR PRINT NAME OIL & GAS INSPECTOR PCT 0 5 1993

Production Supervisor