

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-73

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. V-1146	
7. Unit Agreement Name	
8. Farm or Lease Name Mize-State	
9. Well No. 1	
10. Field and Pool, or Wildcat SE Chaves Queen	
12. County Chaves	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-	2. Name of Operator UPLAND PRODUCTION CO.
3. Address of Operator P.O. BOX 481 MIDLAND, TEXAS 79702	4. Location of Well UNIT LETTER M 660 FEET FROM THE South LINE AND 330 FEET FROM THE West LINE, SECTION 35 TOWNSHIP 12 S RANGE 31 E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4421.6 G.L.	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well non-commercial propose to plug and abandon as follows:

Set 35 sx. plug @ 2945-PBD 3045"

Set 15 sx. plug @ surface.(Cement tied into *-5/8" surface csg.)

Cut off csg. weld on dry hole marker, clean location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W. S. McCay</u>	TITLE <u>Operator's Agent</u>	DATE _____
ORIGINAL SIGNED BY JERRY SEXTON		
APPROVED BY <u>DISTRICT 1 SUPERVISOR</u>	TITLE _____	DATE <u>DEC 10 1984</u>
CONDITIONS OF APPROVAL, IF ANY:		