BBS, NEW MEYNBR 10 TICES	AND REPORTS	ON WELLS back to a different reservoir.	Expires August 31, 1985  5. Lease designation and serial no.  NM 0347394  6. IF INDIAN, ALLOTTEE OR TRIBE NAME
OIL TO GAS T	······································	<del> </del>	7. UNIT AGREEMENT NAME
WELL X WELL OTHER			S. FARM OR LEASE NAME
Fred G. Yates, Inc.	itis Enny	101 CAN	Soth Tomahawk Federal
ADDRESS OF OPERATOR	•	¥	9. WELL NO.
Sunwest Centre Suite 1010  LOCATION OF WELL (Report location clearly See also space 17 below.) At surface	D. Roswell, New Mand in accordance with any	Mexico 88201 y State requirements.*	10. FIELD AND POOL, OR WILDCAT
1980' FSL & 660' FEL			Tomahawk San Andres 11. SEC., 7., B., M., OR BLK. AND SURVEY OR AREA
PERMIT NO.   15.	ELEVATIONS (Show whether p	F, RT, GR, etc.)	Sec. 6, T-885, R32E
	4517_GL	· 	Chaves
Check Approp		Nature of Notice, Report, o	
NOTICE OF INTENTION 1			SEQUENT EMPORT OF:
TEST WATER SHUT-OFF PULL C	OR ALTER CASING	WATER SHUT-OFF	BEPAIRING WELL
FRACTURE TREAT MULTII SHOOT OR ACIDIZE ABANDO	PLE COMPLETE	FRACTURE TREATMENT	ALTERING CASING
	E PLANS	SHOOTING OR ACIDIZING (Other)	ABANDONMENT®
(Other)	[]	(Note: Report resi Completion or Reco	ults of multiple completion on Well supletion Report and Log form.)
1. POH w/rods, tbg, and	d pkr.	acions and measured and true vei	rtical depths for all markers and zones perti
1. POH w/rods, tbg, and 2. Set CIBP @ 4150', mm 3. Cut csg. @ 3181', POH w/2 3/8" tbg. & 6. Spot 35 sack cmt plus 5. GIH w/2 3/8" tbg. & 6. Spot 35 sack cmt plus 7. Tag cmt plug top @ 15.	d pkr. ud up hole, spot OH & lay down 4 : ug @ 3231'. tag cmt plug top ug @ 1852'.	5 sack cmt plug (50	or top of CIBP.
1. POH w/rods, tbg, and 2. Set CIBP @ 4150', mm 3. Cut csg. @ 3181', POH w/2 3/8" tbg. & GIH w/2 3/8" tbg. & 6. Spot 35 sack cmt plus top @ 1. Tag cmt plug top @ 1. Spot 10 sack cmt plus top @ 1.	d pkr.  ud up hole, spot  OH & lay down 4  ug @ 3231'.  tag cmt plug top  ug @ 1852'.  1700'.  ug @ surface & in  TITLE  Approved as to plugstop  Approved as to plugstop	5 sack cmt plug (50 1/2" csg. p @ 3115'.  nstall dry hole mark  Production Analyst  mg of the well bore. s retained until	o') on top of CIBP.
1. POH w/rods, tbg, and 2. Set CIBP @ 4150', mi 3. Cut csg. @ 3181', Pour csg. @ 3181', P	d pkr.  ud up hole, spot  OH & lay down 4 in  ug @ 3231'.  tag cmt plug top  ug @ 1852'.  1700'.  ug @ surface & in  and correct  TITLE	5 sack cmt plug (50 1/2" csg. p @ 3115'.  nstall dry hole mark  Production Analyst  mg of the well bore. s retained until	DATE 5-12-87

ř