N. M. TOIL CONS. COMMISSION P. O. BOX 1980 MODES NA SCIAL

R ORI OF UNDESTRABLE EVENT CHECKL :

DATE OF OCCURRENCE/DISCOVERY: 3-7-89 TIME OF OCCURRENCE app. 9:00 pm
DATE REPORTED TO BLM: 3-8-89 TIME REPORTED: 10:00 am
BLM OFFICE REPORTED TO (RESOURCE AREA/DISTRICT OFFICE/OTHER): Roswell
LOCATION: SECTION: 27 T. 13-S R. 31-E MERIDIAN
COUNTY: Chaves STATE: New Mexico WELL NAME: Wakan Tanka Federal #1
OPERATOR: Dakaota Resources Inc., 310 West Wall, midland, Texas 79701
SURFACE OWNERSHIP (FEDERAL/INDIAN/FEE/STATE): Fee
MINERAL OWNERSHIP (FEDERAL/INDIAN/FEE/STATE): Federal
LEASE NO.: NM-080128 UNIT/CA NO.: RIGHT-OF-WAY NO.: TYPE OF EVENT, CIRCLE APPROPRIATE ITEM(S):
BLOWOUT, FIRE, FATALITY, INJURY, PROPERTY DAMAGE, OIL SPILL, SALTWATER SPILL, TOXIC FLUID SPILL, OIL AND SALTWATER SPILL, OIL AND TOXIC FLUID SPILL, SALTWATER AND TOXIC FLUID SPILL, GAS VENTING, UNCONTROLLED FLOW OF WELLBORE FLUIDS, OR OTHER (SPECIFY): oil overflow due to heater treater malfunction
CAUSE OF EVENT: Heater treater malfunctioned resulting in a gas surge pushing a small amouny of oil out of the vent
CAUSE AND EXTENT OF PERSONAL INJURIES/CAUSE OF DEATH(S):
EFFECTS OF EVENT: minor overflow at tank battery/ heatertreater
ACTION TAKEN TO CONTROL THE EVENT: shut well in and repair heater treater, 2' dikes were in place prior to the vent overflow
LENGTH OF TIME TO CONTROL EVENT AND SUBSEQUENT CLEAN-UP: immediate
ACCEPTED FOR RECORD
VOLUME(S) OF FLUIDS (SPECIFY): DISCHARGED: less than 5 BO CONSUMED: 5 Bo RECOVERED: none
OTHER FEDERAL, STATE, AND LOCAL GOVERNMENT AGENCIES NOTIFIED (INCREMENT AGENCIES NOTIFIED (INCREMENT AGENCIES AND LOCAL GOVERNMENT AGENCIES AND LOCAL GOVERNMENT AGENCIES NOTIFIED (INCREMENT AGENCIES AND LOCAL GOVERNMENT AGENCIE
ROSWELLSRESOURCE AREA
ACTION THAT HAS BEEN OR L. BE TAKEN TO PREVENT RECEIVED: repaired malfunction
SIGNATURE OF OPERATOR (I ORT SUBMITTED BY OP-
TITLE Vice-President