ibmit 3 Copies Appropriate istrict Office	State of New Mexico Energy, 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	o arces Department		Form C-103 Revised 1-1-89
ISTRICT I O. Box 1980, Hobbs, NM 88240	OIL CONSERVATION P.O. Box 2088	DIVISION	WELL API NO. 30-005-21085	
ISTRICT II O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87:	504-2088	5. Indicate Type of Lease STAT	E FEE X
ISTRICT III 000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No.	
DO NOT USE THIS FORM FOR PI	TICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OF ERVOIR. USE "APPLICATION FOR PERMI C-101) FOR SUCH PROPOSALS.)	PLUG BACK 10 A	7. Lease Name or Unit Agreen	nent Name
Type of Well: Oh. GAS WELL XX WELL	OTHER	·	Flying WV	
Name of Operator		• `	8. Well No.	
YATES PETROLEUM CORP	ORATION		9. Pool name or Wildcat	
Address of Operator	eet - Artesia, NM 88210		Tobac Penn	
Well Location	eet – Artesia, Mi 66216	· · ·		
	60 Feet From The	Line and51	0 Feet From The	last Line
Unit Letter				Country
Section 34	Township 8S Rang	e <u>33E</u>	NMPM Chaves	County
	10. Elevation (Show whether Dr 4356' GH			
	k Appropriate Box to Indicate N		Report, or Other Data	
	K Appropriate Box to moleate N	SU	BSEQUENT REPOR	T OF:
NOTICE OF I	NTENTION TO:	00		1
		REMEDIAL WORK		JC CASING 1
				NG CASING l
r		COMMENCE DRILLI		ND ABANDONMENT
				1
r		COMMENCE DRILLI CASING TEST AND		ſ
TEMPORARILY ABANDON		COMMENCE DRILLI CASING TEST AND OTHER:		ND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: d give pertinent dates, in	NG OPNS. PLUG A CEMENT JOB	ND ABANDONMENT
TEMPORARILY ABANDON		COMMENCE DRILLI CASING TEST AND OTHER: give pertinent dates, in	NG OPNS. PLUG A CEMENT JOB	ND ABANDONMENT [
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: is give pertinent dates, in th Yates Petro nd abandon well	NG OPNS. PLUG A CEMENT JOB	ND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: d give pertinent dates, in th Yates Petro nd abandon well on top.	NG OPNS. PLUG A CEMENT JOB	ND ABANDONMENT
TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 12 Describe Proposed or Completed O work) SEE RULE 1103. Verbal permission wa Kautz with the OCD o 1. Set CIBP at 9250 2. Set 100' cement 3. Set 100' cement	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:	NG OPNS. PLUG A CEMENT JOB cluding estimated date of starting oleum Corporation fr .1 as follows: and below). 5132' (50' above an 350' (50' above and	ABANDONMENT
TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 12 Describe Proposed or Completed O work) SEE RULE 1103. Verbal permission wa Kautz with the OCD o 1. Set CIBP at 9250 2. Set 100' cement 3. Set 100' cement	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:	NG OPNS. PLUG A CEMENT JOB cluding estimated date of starting oleum Corporation fr .1 as follows: and below). 5132' (50' above an 350' (50' above and	ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: is give pertinent dates, in th Yates Petro nd abandon well on top. 5' (50' above Glorieta at 3 ing shoe at 3 nt plug across	NG OPNS. PLUG A CEMENT JOB	ND ABANDONMENT any proposed rom Paul d below). below). b (50'
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: is give pertinent dates, in th Yates Petro nd abandon well on top. 5' (50' above Glorieta at 3 ing shoe at 3 nt plug across	NG OPNS. PLUG A CEMENT JOB	nD ABANDONMENT any proposed rom Paul d below). below). b (50'
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: is give pertinent dates, in th Yates Petro nd abandon well on top. 5' (50' above Glorieta at 3 ing shoe at 3 nt plug across	NG OPNS. PLUG A CEMENT JOB	ND ABANDONMENT any proposed rom Paul d below). below). b (50'
TEMPORARILY ABANDON DULL OR ALTER CASING DTHER: 12 Describe Proposed or Completed O work) SEE RULE 1103. Verbal permission wa Kautz with the OCD of 1. Set CIBP at 9250 2. Set 100' cement 3. Set 100' cement 4. Set 100' cement 5. Cut and pull 5- above and below 6. Set 100' cement 7. Set 10 sack cem 8. Install regulat	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER: igive pertinent dates, in th Yates Petro nd abandon well on top. 5' (50' above Glorieta at 3 ing shoe at 3 nt plug across Rustler at 20	NG OPNS. PLUG A CEMENT JOB	ND ABANDONMENT any proposed rom Paul d below). below). b (50'
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:	NG OPNS. PLUG A CEMENT JOB	ND ABANDONMENT any proposed rom Paul d below). below). b (50'
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:	NG OPNS. PLUG A CEMENT JOB C cluding estimated date of starting of eum Corporation fr 1 as follows: and below). 5132' (50' above and 550' (50' above and 55-1/2" casing stu 050' (50' above and 050' (50' above and 09ERATIONS.	ND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:	NG OPNS. PLUG A CEMENT JOB cluding estimated date of starting oleum Corporation fr 1 as follows: and below). 5132' (50' above and 550' (50' above and 550' (50' above and 050' (50' above and	nD ABANDONMENT
EMPORARILY ABANDON DULL OR ALTER CASING DTHER: 12 Describe Proposed or Completed O work) SEE RULE 1103. Verbal permission wa Kautz with the OCD of 1. Set CIBP at 9250 2. Set 100' cement 3. Set 100' cement 4. Set 100' cement 5. Cut and pull 5- above and below 6. Set 100' cement 7. Set 10 sack cem 8. Install regulat NOTIFY OCD (393-616 I hereby certify that the information above sionATURE DULL OR ALTER CASING DULL OR ALTER DULL OR ALTER CASING DULL OR ALTER CIBP AT 9250 DULL OR ALTER CIBP AT 9250 DULL OR ALTER DULL OR ALTER CIBP AT 9250 DULL OR ALTER DULL OR ALTER CIBP AT 9250 DULL OR ALTER CIBP AT 9250 DULL OR ALTER DULL OR ALTER CIBP AT 9250 DULL OR ALTER CIBP AT 925	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:	NG OPNS. PLUG A CEMENT JOB cluding estimated date of starting oleum Corporation fr 1 as follows: and below). 5132' (50' above and 55-1/2" casing stu 050' (50' above and 050' (50' (50' (50' (50' (50' (50' (50'	ABANDONMENT any proposed rom Paul d below). below). b (50' below).
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:	NG OPNS. PLUG A CEMENT JOB cluding estimated date of starting oleum Corporation fr 1 as follows: and below). 5132' (50' above and 55-1/2" casing stu 050' (50' above and 050' (50' (50' (50' (50' (50' (50' (50'	ND ABANDONMENT
EMPORARILY ABANDON DULL OR ALTER CASING DTHER: 12 Describe Proposed or Completed O work) SEE RULE 1103. Verbal permission wa Kautz with the OCD of 1. Set CIBP at 9250 2. Set 100' cement 3. Set 100' cement 4. Set 100' cement 5. Cut and pull 5- above and below 6. Set 100' cement 7. Set 10 sack cem 8. Install regulat NOTIFY OCD (393-616 I hereby certify that the information above sionATURE DULL OR ALTER CASING DULL OR ALTER DULL OR ALTER CASING DULL OR ALTER CIBP AT 9250 DULL OR ALTER CIBP AT 9250 DULL OR ALTER DULL OR ALTER CIBP AT 9250 DULL OR ALTER DULL OR ALTER CIBP AT 9250 DULL OR ALTER CIBP AT 9250 DULL OR ALTER DULL OR ALTER CIBP AT 9250 DULL OR ALTER CIBP AT 925	CHANGE PLANS	COMMENCE DRILLI CASING TEST AND OTHER:	NG OPNS. PLUG A CEMENT JOB C cluding estimated date of starting oleum Corporation fr 1 as follows: and below). 5132' (50' above and 55-1/2" casing stu 050' (50' above and 050' (50' (50' above and 050' (50' (50' (50' (50' (50' (50' (50'	ND ABANDONMENT

aer.=IV=D

אסטי איטע איטע פרקואב

.~