NO. OF COPIES RECEI	VED						Form C-103	I
DISTRIBUTION							Supersedes C-102 and (
SANTA FE NEW MEXICO OIL CONSERVATION COMMISSION							Effective 1	
FILE						_		
U.S.G.S.						50	. Indicate Ty State	
LAND OFFICE						-		Fee Gas Lease No.
OPERATOR						, ,		ada Ecdae No.
	CULIDA	LIOTICES	AND DEDORT	COLLWELLS			B-11447	emmenne.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)								
1.	OSE APPEICATIO	N 1 OK 1 EKWITT -	- (, Gillin G (G)) (7.	Unit Agreem	ient Name
OIL X	GAS WELL	OTHER-				North	Caprock	Queen Unit 2
2. Name of Operator						8	Form or Lec	ise Name
34100	Supply Son	YY KNOZ	Anadar	rko Produc	tion Co.		Tract #	9
3. Address of Operator						9	. Well No.	
	Box 647	Artes	sia, New Mea	<u>cieo 8821</u>	0		#1	Pool, or Wildcat
4. Location of Well		000	w		600	'		_
UNIT LETTER	<u>E 1</u>	980 FEET	FROM THE	DETE LINE A	ло <u>660</u> г	FEET FROM	Caprook	
THE West		7	•	L3-S ∂à ⊶	357-5			
THE THE	LINE, SECTION	·	TOWNSHIP	LU U RM	NGE AVE D	имрм.		
		15. 1	Elevation (Show w	hether DF, RT,	GR, etc.)	1	2. County	
				4399 GL			Lea	
16.	Check A	ppropriate	Box To Indica	ate Nature o	f Notice, Repor	rt or Other	Data	
ı	NOTICE OF IN	TENTION T	0:	ı	subsi	EQUENT F	REPORT O	F:
						 -		L1
PERFORM REMEDIAL W	ORK		PLUG AND ABANDON	REMEDIA	AL WORK		ALT	ERING CASING
TEMPORARILY ABANDON	· _				CE DRILLING OPNS.		PLU	G AND ABANDONMENT
PULL OR ALTER CASING	• 📖		CHANGE PLANS	<u> </u>	TEST AND CEMENT JQB	· []		[]
OTHER				OTHE				
					·		·	
17. Describe Proposed work) SEE RULE		erations (Clear	ly state all pertine	ent details, and	give pertinent dates,	including es	timated date	of starting any proposed
•	plug and ab	andon wel	ll as follo	V8:1				
	ull tubing		•					
2. S	et cast iro	n bridge	plug at bas	se of 54"	casing appro	ximately	3005.	
3. Spot 25 foot cement plug on top of bridge plug.								
4. K	nock off oi	1 string	at free po	int. appro	wimately 120	01.		
4. Knock off oil string at free point, approximately 1200'.								
5. Set 25 sack cement plug at casing out off point.								
6. Set 10 Sack cement plug at surface.								
7. Set surface marker.								
8. Remove all equipment and clean up location.								
No castos	rill: temped	101-12-12	WELL.					
25	5X5 in	t on	tof	547 Fe	re c	59. 51	hoe	
, ,					1 plugs			
18. I hereby certify th	at the information	above is true	and complete to the	best of my kno	wledge and belief.	-		

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE SUPERVISOR DISTRICT I DATE NOV 8 1971

1, 1, 1, 1, 2

et in the experience of the ex

Control of the Contro

the extra consistency of the contract of a c

experience of the second of th

RECEIVED

Harry - 0 1971

OIL CONSTRUMMEN COURT.

The Common transfer of the second section is a second section of

and the second of the second o