

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>		5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
		5. State Oil & Gas Lease No. E 7555
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		7. Unit Agreement Name
2. Name of Operator McGrath & Smith, Inc.		8. Farm or Lease Name Tidewater State
3. Address of Operator 310 West Texas Suite 418, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER J 2310 FEET FROM THE South LINE AND 2310 FEET FROM THE E LINE, SECTION 18 TOWNSHIP 13-S RANGE 32-E NMPM.		10. Field and Pool, or Wildcat Caprock Queen
15. Elevation (Show whether DF, RT, GR, etc.) 4376 GL 4382 KB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/> CASING TEST AND CEMENT JOBS <input type="checkbox"/> OTHER <input type="checkbox"/>		SUBSEQUENT REPORT OF: ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> OTHER <input type="checkbox"/>
--	--	---

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1705.

We plan to P & A 1-8-69 by the following:

1. Cut 4½ off @ 2629'
2. Put 25 sx. over perforations from 3052'-58
3. Put 25 sx. at cut off point
4. Put 25 sx. at top of salt at 1500'
5. Put 25 sx. in and out of 8-5/8" shoe at 309'-some below and some in
6. Put 10 sx. on top.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>J.B. Taylor</u>	TITLE <u>Engineer</u>	DATE <u>1-6-69</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>JAN 8 1969</u>
CONDITION OF APPROVAL, IF ANY:		