					<u> </u>
Submit 3 Copies	State of New Mex Energy, Minerals and Natural Res		1	Form C-103 Revised 1-1-89	1
lo Appropriate District Office	Energy, Wintering and Pulling and			Actual 1 1 05	
DISTRICT I	OIL CONSERVATIO	N DIVISION	WELL API NO.		
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088			30-025-01097		
Santa Fe, New Mexico 87504-2088 O. Drawer DD, Artesia, NM 88210		5. Indicate Type of Lease STATE X FEE		 	
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410			6. State Oil & Gas Lease No. V-3834		
	TIOFO AND DEPODTS ON WEL				
(DO NOT USE THIS FORM FOR F DIFFERENT RES (FORM	DTICES AND REPORTS ON WEL PROPOSALS TO DRILL OR TO DEEPEN SERVOIR. USE "APPLICATION FOR PER A C-101) FOR SUCH PROPOSALS.)	OR PLUG BACK TO A	7. Lease Name or U	nit Agreement Name	
. Type of Well: OIL GAS WELL XX WELL [Workov	ver	Sapphire Al	LE State	
Name of Operator		<u> </u>	8. Well No.		
YATES PETROLEUM CORPO	ORATION		1		
Address of Operator			9. Pool name or Wi Lazy J Penn	dcat	
105 South 4th St., A	rtesia, NM 88210	······································	Lazy 5 Tellin		
Well Location Unit Letter \underline{I} : <u>19</u>	980 Feet From The South	Line and660) Feet From 7	he East L	ine
Section 33	Township 13S Ran	nge 33E	NMPM Lea	County	v
Section 5.5	10 In Elevation (Show whether I	DF, RKB, RT, GR, etc.)			
	4248' GR				
1. Chec	ck Appropriate Box to Indicate N	Nature of Notice, F	Report, or Other	Data	
	NTENTION TO:		BSEQUENT RE		
		REMEDIAL WORK		LTERING CASING	
EMPORARILY ABANDON		COMMENCE DRILLIN	g opns. 🗌 F	PLUG AND ABANDONMENT	· 🗌
	CHANGE PLANS	COMMENCE DRILLIN		PLUG AND ABANDONMENT	· 🗌
DTHER: <u>Squeeze perfs</u> ,] NO ZONE CHANGE perforate additional [X]	CASING TEST AND C			·
ULL OR ALTER CASING DTHER: <u>Squeeze perfs</u> , 1 12. Describe Proposed or Completed Of work) SEE RULE 1103. This well was deepen to shut off the wath 1) POH with pump. 2) RIH with 4" cem. 3) Squeeze perfs 9 4) RIH w/tubing an. 5) POH w/tubing an. 6) Perforate throw 7) TOH w/perf guns 8) Acidize perfs 9	NO ZONE CHANGE perforate additional X perations (Clearly state all pertinent details, and ned and completed in Bou er zone and add AB perfor ent retainer. Set retain 947-98', 10001-10035'. d packer. Swab perforation d packer. RIH w/N-80 tubin ugh tubing guns 9684-9714	CASING TEST AND C OTHER: of give pertinent dates, incl agh A-F zones, ations. her @ ±9920'. ons 9654-9856'. ing open-ended ' w/14 holes-1 C NEFE acid.	EMENT JOB uding estimated date of . July 1992. T Evaluate. into top of 1	starting any proposed his workover will	
ULL OR ALTER CASING DTHER: <u>Squeeze perfs</u> , 1 12. Describe Proposed or Completed Of work) SEE RULE 1103. This well was deepen to shut off the wath 1) POH with pump. 2) RIH with 4" cemu 3) Squeeze perfs 9 4) RIH w/tubing an 5) POH w/tubing an 6) Perforate thro 7) TOH w/perf guns 8) Acidize perfs 9 9) Swab entire per	NO ZONE CHANGE perforate additional X perations (Clearly state all pertinent details, and ned and completed in Bou er zone and add AB perfor ent retainer. Set retain 947-98', 10001-10035'. d packer. Swab perforation d packer. RIH w/N-80 tubin ugh tubing guns 9684-9714 and tubing. 684-9727' w/4000 gals 15% forated interval 9654-985	CASING TEST AND C OTHER: of give pertinent dates, incl agh A-F zones, ations. er @ ±9920'. ons 9654-9856'. ng open-ended ' w/14 holes-1 & NEFE acid. 56'.	EMENT JOB uding estimated date of . July 1992. T Evaluate. into top of 1	starling any proposed his workover will	
ULL OR ALTER CASING DTHER: <u>Squeeze perfs</u> , 1 12. Describe Proposed or Completed Of work) SEE RULE 1103. This well was deepen to shut off the wath 1) POH with pump. 2) RIH with 4" cemu 3) Squeeze perfs 9 4) RIH w/tubing an 5) POH w/tubing an 6) Perforate thro 7) TOH w/perf guns 8) Acidize perfs 9 9) Swab entire per	NO ZONE CHANGE perforate additional X perations (Clearly state all pertinent details, and ned and completed in Bou er zone and add AB perfor ent retainer. Set retain 947-98', 10001-10035'. d packer. Swab perforation d packer. RIH w/N-80 tubin ugh tubing guns 9684-9714 and tubing. 684-9727' w/4000 gals 15% forated interval 9654-985 is true, and complete to the best of my knowledge and	CASING TEST AND C OTHER: of give pertinent dates, incl agh A-F zones, ations. er @ ±9920'. ons 9654-9856'. ng open-ended ' w/14 holes-1 & NEFE acid. 56'.	EMENT JOB	skarling any proposed his workover will iner.	
ULL OR ALTER CASING DTHER: <u>Squeeze perfs</u> , <u>1</u> 12. Describe Proposed or Completed Of work) SEE RULE 1103. This well was deepen to shut off the wath 1) POH with pump. 2) RIH with 4" cem 3) Squeeze perfs 9 4) RIH w/tubing an 6) Perforate thro 7) TOH w/perf guns 8) Acidize perfs 9 9) Swab entire per I hereby certify that the information above is SKONATURE	NO ZONE CHANGE perforate additional X perations (Clearly state all pertinent details, and ned and completed in Bou er zone and add AB perfor ent retainer. Set retain 947-98', 10001-10035'. d packer. Swab perforation d packer. RIH w/N-80 tubin ugh tubing guns 9684-9714 and tubing. 684-9727' w/4000 gals 15% forated interval 9654-985 is true, and complete to the best of my knowledge and	CASING TEST AND C OTHER: ad give pertinent dates, incl agh A-F zones, ations. her @ ±9920'. ons 9654-9856'. ng open-ended ' w/14 holes-1 2 NEFE acid. 56'.	EMENT JOB	skarling any proposed his workover will iner.	atte
ULL OR ALTER CASING THER: <u>Squeeze perfs</u> , 1 12. Describe Proposed or Completed Of work) SEE RULE 1103. This well was deepen to shut off the wath 1) POH with pump. 2) RIH with 4" cem 3) Squeeze perfs 9 4) RIH w/tubing an 5) POH w/tubing an 6) Perforate thro 7) TOH w/perf guns 8) Acidize perfs 9 9) Swab entire per I hereby certify that the information above is SIONATURE Juan	NO ZONE CHANGE perforate additional X perations (Clearly state all periment details, and ned and completed in Bou er zone and add AB perfor ent retainer. Set retain 947-98', 10001-10035'. d packer. Swab perforation d packer. RIH w/N-80 tubin ough tubing guns 9684-9714 and tubing. 684-9727' w/4000 gals 15% forated interval 9654-985 is true and complete to the best of my knowledge and Date of the	CASING TEST AND C OTHER: ad give pertinent dates, incl agh A-F zones, ations. her @ ±9920'. ons 9654-9856'. ng open-ended ' w/14 holes-1 2 NEFE acid. 56'.	EMENT JOB	naring any proposed his workover will iner	atte
ULL OR ALTER CASING THER: <u>Squeeze perfs</u> , 1 12. Describe Proposed or Completed Of work) SEE RULE 1103. This well was deepen to shut off the wath 1) POH with pump. 2) RIH with 4" cem 3) Squeeze perfs 9 4) RIH w/tubing an 5) POH w/tubing an 6) Perforate thro 7) TOH w/perf guns 8) Acidize perfs 9 9) Swab entire per I hereby certify that the information above is SIONATURE Juan	NO ZONE CHANGE perforate additional X perations (Clearly state all periment details, and ned and completed in Bou er zone and add AB perfor ent retainer. Set retain 947-98', 10001-10035'. d packer. Swab perforation d packer. RIH w/N-80 tubin ough tubing guns 9684-9714 and tubing. 684-9727' w/4000 gals 15% forated interval 9654-985 is true and complete to the best of my knowledge and Date of the best of the best of the best of my knowledge and Date of the best of the be	CASING TEST AND C OTHER: ad give pertinent dates, incl agh A-F zones, ations. her @ ±9920'. ons 9654-9856'. ng open-ended ' w/14 holes-1 2 NEFE acid. 56'.	EMENT JOB	naring any proposed his workover will iner	atte