

NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

HOBBS OFFICE 000

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL	XX	NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)		NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICOHOBBS, NEW MEXICO
(Place)October 13, 1958
(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the.....

SINCLAIR OIL & GAS COMPANY **STATE 245** Well No. **7** in **8**
(Company or Operator) **Lease** (Unit)

SW $\frac{1}{4}$ **NE** $\frac{1}{4}$ of Sec. **33**, T. **13S**, R. **33E**, NMPM., **Lang-J. Pass.** Pool
(40-acre Subdivision)

Lee County.

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

9653PB

13 3/8"OD Casing set @ 307' w/ 350 Sks. - Cement circulated to surface
 @ 5/8"OD " 4059' w/ 1700 Sks. - Top cement behind @ 5/8"OD Casing @ 890'
 5 1/2"OD " 9700' w/ 250 Sks. - Top cement behind 5 1/2"OD Casing @ 8498'
 Perforations f/ 9604 to 9673'
 Reason for plugging- Production dropped

FOLLOWING PROPOSED PLUGGING PROCEDURE:

Spot 25 Sks. cement plug f/ 9448 to 9653' - keeping hole full heavy mud.
 Run Magnetometer and cut 5 1/2"OD Casing off @ Approx. 8498' and pull.
 Spot 25 Sks. cement plug in 5 1/2"OD Casing stub and 25 Sks. cement plug f/ 4020 to 4100' keeping
 hole full heavy mud

Run Magnetometer and cut @ 5/8"OD Casing off @ Approx. 890' and pull.
 Spot 25 Sks. cement plug in stub of @ 5/8"OD Casing and 25 Sks. cement plug f/ 290 to 321'
 keeping hole full heavy mud.

Spot 15 Sks. cement plug in bottom of collar & top of 13 3/8"OD Casing w/ 4" Regulation Marker on
 landing 4' above surface level - Fill Collar & Level location P&A operation Complete.

Approved....., 19.....

Sinclair Oil & Gas Company

By.....

Position.....

Dist. Supt.

Send Communications regarding well to:

Approved

OIL CONSERVATION COMMISSION

By.....

Name.....C. C. Salter, 520 E. Broadway

Title.....

Address.....Hobbs, N.M.