## Submit 3 Copies to Appropriate District Office

## State of New Mexico gy, Minerals and Natural Resources Departme

DISTRICT I P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION

Form C	-103
Revised	1-1-89

P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088		WELL API NO.
DISTRICT II P.O. Drawer DD, Artesia, NM 88210  Santa Fe, New Mexico	87504-2088	5. Indicate Type of Lease
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE X
		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WE	LLS	
( DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"		7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:		_
OIL GAS WELL OTHER		Stevens
2. Name of Operator		8. Well No.
Charles B. Gillespie, Jr.  3. Address of Operator		6
P. O. Box 8 Midland, Texas 79702		9. Pool name or Wildcat Saunders Permo Upper Penn
4. Well Location	· · · · · · · · · · · · · · · · · · ·	
Unit Letter $B : 660$ Feet From The North	Line and198	CO Feet From The East Line
Section 33 Township 14-S	tange 33-E j	NMPM Lea County
10. Elevation (Show whether	r DF, RKB, RT, GR, etc.)	NMPM Lea County
4219 D		
Check Appropriate Box to Indicate NOTICE OF INTENTION TO:		
	SOB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING	OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB	
OTHER:	OTHER:	
12. Describe Proposed or Completed Operations (Clearly state all pertinent details, a		
work) SEE RULE 1103.	na give pertinent aates, includ	ing estimated date of starting any proposed
1 Sot cost iven builty 1		
<ol> <li>Set cast iron bridge plug above per Dump 4 sx cement on top of bridge p</li> </ol>	forations at 977!	5'.
2. Set 25 sx plug at 7700', across ton	of ABO	
3. Set 50 sx plug across liner top at A	1014', Tag.	
4. Lut off and pull 8 5/8" casing from	approximately 20	000'.
5. Set 25 sx plug across 8 5/8" casing 6. Set 25 sx plug at 1600' across top of	stub.	
6. Set 25 sx plug at 1600' across top of 7. Set 25 sx plug at 294' across base of		
7. Sec 23 SX pluy at 294 across base of	of salt.	
8. Set 10 sy plug at top of supface and	of 13 3/8" casino	g shoe.
8. Set IU sx plug at top of surface cas	of 13 3/8" casino Sina.	g shoe.
8. Set IU sx plug at top of surface cas	of 13 3/8" casino Sina.	g shoe.
8. Set IU sx plug at top of surface cas	of 13 3/8" casino Sina.	g shoe.
9. Weld 4" marker to surface pipe, and	of 13 3/8" casing sing. clean location.	g shoe.
9. Weld 4" marker to surface pipe, and  Thereby certify that the unformation above is true and complete to the best of my knowledge and	of 13 3/8" casing sing. clean location.	
9. Weld 4" marker to surface pipe, and  I hereby certify that the information above is true and complete to the best of my knowledge and signature  Marker to surface pipe, and	of 13 3/8" casing sing. clean location.	Sanager DATE 6/6/89
9. Weld 4" marker to surface pipe, and  Thereby certify that the information above is true and complete to the best of my knowledge and signature  TYPE OR PRINT NAME  David W. Hastings	of 13 3/8" casing sing. clean location.	
9. Weld 4" marker to surface pipe, and  I hereby certify that the utformation above is true and complete to the best of my knowledge and  SIGNATURE David W. Hastings  (This space for State Use)	of 13 3/8" casing sing. clean location.	1anager DATE 6/6/89 TELEPHONE NO915-683-176
9. Weld 4" marker to surface pipe, and  I hereby certify that the information above is true and complete to the best of my knowledge and  signature	of 13 3/8" casing sing. clean location.	Manager DATE 6/6/89