NO. OF COPIES RECEIVED	7	Form C-103
DISTRIBUTION		Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	Effective 1-1-65
FILE		
U.S.G.S.		5a. Indicate Type of Lease State X Fee
LAND OFFICE		
OPERATOR		5. State Oil & Gas Lease No.
		7 a fical
(DO NOT USE THIS FORM FOR P	RY NOTICES AND REPORTS ON WELLS ROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. ATION FOR PERMIT " (FORM C-1C1) FOR SUCH PROPOSALS.)	
<u>Гі.</u>		7. Unit Agreement Name
	OTHER. Water Injection	Ranger Lake Unit
2. Name of Operator		8. Farm or Lease Name
Phillips Petroleum (Company	Ranger Lake Unit, Tract2
3 Address of Operator		9. Well No.
Room 711, Phillips H	Building, Odessa, Texas 79761	->₩-1.
2 11/ 11	660 FEET FROM THE South LINE AND 660 FEET FRO	10. Field and Pool, or Wildcat
UNIT LETTER	FEET FROM THE LINE AND FEET FRO	
east	100 23 TOWNSHIP 12-S RANGE 34-E	//////////////////////////////
THE ENC, OU		VIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
	15. Elevation (Show whether DF, RT, CR, etc.)	Lea
	4151' DF	Tea UIIIIII
	Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
NOTICE OF	INTENTION TO: SUBSEQUEN	T REPORT OF:
	PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
PERFORM REMEDIAL WORK	COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
TEMPORARILY ABANDON	CHANGE PLANS CASING TEST AND CEMENT JOP	
PULL OR ALTER CASING	OTHER	
07115.0		
OTHER	(Charle and all partinent details, and give pertinent dates, includin	internet data of starting any proposed
	(c) 1	a estimated date of starting any proposed

17. Describe Proposed or Completed Operations (Clearly work) SEE RULE 1103.

MI well service unit, unlatch tubing from packer. Locate tubing in packer at 10,205', cement perfs 10,270-351' with 100 sx Class H cmt w/0.3% LWL w/1# Gilsonite per sx. Pick up out of packer, load hole w/25 sx gel per 100 bbls water. With temperature survey TOC at 4975', shoot 5-1/2" csg at free point and recover. Run tubing and spot 30 sx cement from 50' below casing cut to 50' above cut. If cut is below 4250', spot 40 sx Class H cement from 4253' across 9-5/8" casing shoe. Pull tubing. Cut off wellhead, spot 10 sx cment from 30' to surface. Install well marker.

24 hr notice

Amore Production Company, Box 68, Hobbs, New Mexico 88240 cc:

18. 1 hereby derisity that the information above is true and complete		DATE 2-15-73
Orig. Signed by	- TITLE	DATE