

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-05020

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
SMITH AND MARRS, INC.

3. Address of Operator
1110 N. BIG SPRING MIDLAND, TX 79601

4. Well Location
Unit Letter P : 330 Feet From The S Line and 660 Feet From The E Line
Section 13 Township 12S Range 37E NMPM LEA County

10. Elevation (Show whether ~~DF~~, ~~RKB~~, ~~RF~~, GR, etc.)
3881'

7. Lease Name or Unit Agreement Name

SHULTS

8. Well No.
2

9. Pool name or Wildcat
GLADIOLA - WOLFCAMP

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Rig up pulling unit, pull production equipment
- 2) Set CIBP at 9350' and cap with 35' cmt.
- 3) Load hole with 10# gel between all plugs.
- 4) Take free point
- 5) If not free at Abo set 100' plug at 7700'
- 6) Cut and pull 5 1/2" casing. Set 100' plug at stub 50' in and 50' out and tag.
- 7) Set 100' plug at 8 5/8" shoe 50' in and 50' out and tag.
- 8) Check free point on 8 5/8", if free cut and pull, spot 100' plug 50' in and 50' out
- 9) Set 100' plug at top of Salt at 2260'
- 10) Set 10 sx plug at surface, install dry hole marker, and clean location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Michael L. Pierce TITLE Agent DATE 5-8-91

TYPE OR PRINT NAME Michael L. Pierce TELEPHONE NO. 392-1915

(This space for State Use)

Orig. Signed by
Paul Kautz
Geologist

APPROVED BY _____ TITLE _____ DATE MAY 09 1991

CONDITIONS OF APPROVAL, IF ANY: